



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE (SINGAPORE)		NAME : Ho Whei Li		WIP : 14149	
3 Anson Road		ADDRESS : 127 Branksome Road		EXCESS :	
#16-00 Springleaf Tower		Singapore 439643		DATE: 15-Feb-21	
Singapore 079909		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SLQ1R	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ97ZHL132287	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	Panamera 4S Diesel	DATE REG.:	21-Sep-17	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY	1ST	SUPP	REVISED	PRICES
1	FRONT DOOR LH	1		P971-831-021- Y-GRV	\$ 2,980.70
2	HINGE LH UPPER	2		P9A7-833-407-01-	\$ 76.20
3	HINGE LH LOWER	2		P9A7-833-405-01-	\$ 89.20
4	HINGE LH A- PILLAR	2		P9A7-831-403-00-	\$ 77.00
5	DOOR SEAL FRONT END	1		P971-837-773- -	\$ 72.80
6	FRONT DOOR SEAL LOWER	1		P971-837-511-A -	\$ 75.10
7	DOOR SEAL OUTER	1		P971-837-911- -	\$ 249.80
8	CLAMP	1		P971-837-073- -	\$ 3.40
9	RIVET	4		PN -906-531-01-	\$ 6.80
10	BLIND RIVET NUT	8		PN -910-167-02-	\$ 17.60
11	CLIP	2		PN -905-417-01-	\$ 1.60
12	STOP	1		P9A7-860-385-00-	\$ 12.40
13	DOOR CHECKER FRONT LH	1		P971-837-179-A -	\$ 279.20
14	BLIND RIVET NUT	2		PN -910-167-02-	\$ 4.40
15	BLIND RIVET NUT	4		PN -912-336-01-	\$ 5.20
16	P000-043-305-51-/CAVITY PRESERVATION (AK	1		P000-043-210-97-	\$ 70.90
17	P958-537-437-40-/(WH17) ADHESIVE TAPE DO	1		PV04-015-800-B -	\$ 126.30
18	DOOR HANDLE FRONT LH	1		P971-837-205-EY-G2X	\$ 587.20
19	MOUNTING BAR FOR FRONT DOOR	1		P971-839-885-E -	\$ 171.70
20	DESK PAD	1		P971-837-209- -	\$ 20.80
21	DESK PAD	1		P971-837-277- -	\$ 20.80
22	PROTECTION CAP	1		P971-839-330- -	\$ 10.70
23	BOWDEN CABLE	1		P971-837-085- -	\$ 39.10
24	FRONT SOOR STRIKER LH	1		P9A7-837-033-00-	\$ 37.20
25	DOOR LOCK LH	1		P971-837-015-D -	\$ 542.20
26	DRIVE UNIT FRONT DOOR LH	1		P9A7-837-059- -	\$ 848.50
27	REAR DOOR SEAL FRONT END	1		P971-839-773- -	\$ 59.20
28	MIRROR HOUSING LH	1		P971-857-527-A -G2X	\$ 331.80
29	MIRROR HOUSING LOWER LH	1		P971-857-185-L -041	\$ 187.40
30	FRONT DOOR OUTER MOULDING LH	1		P971-837-475-B -041	\$ 509.10
31	REAR DOOR OUTER MOULDING LH	1		P971-839-475-B -041	\$ 464.30
32	STONE GUARD FILM LH	1		P971-853-823- -	\$ 113.00
33		0		0	\$ -

	TOTAL PARTS							\$ 8,091.60
								\$ -
	TOTAL PARTS COST							\$ 8,091.60
SUPPLEMENTARY								
NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES	
1								
2								
3								
	Labour Description							
1	TO REMOVE /INSTALL FRONT DOOR LH, SIDE MIRROR COVER LH & ALL DAMAGED BODY						\$ 3,900.00	
	PARTS. TO REPAIR REAR DOOR LH & ALL AREAS AFFECTED BY THE ACCIDENT.							
2	TO RESPRAY FRONT DOOR LH, REAR DOOR LH, SIDE MIRROR COVER LH .						\$ 3,300.00	
3	TO CARRY-OUT BODY CAVITY PRESERVATION.						\$ 250.00	
4	TO TRANSFER THE FRONT DOOR LH MECHANISM					NETT	\$ 780.00	
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.						\$ 250.00	
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					NETT	\$ 600.00	
7	SUNDRIES.					NETT	\$ 50.00	
		TOTAL LABOUR				\$ -	\$ 9,130.00	
		TOTAL PARTS				\$ -	\$ 8,091.60	
		TOTAL				\$ -	\$ 17,221.60	
		LESS EXCESS				\$ -	\$ -	
		TOTAL AFTER EXCESS				\$ -		
		GST 7%				\$ -	\$ -	
		GRAND TOTAL				\$ -	\$ -	