

ASS. REC. BY:

REF: CS3/MSG21002216/R1vf3

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)From (Person): JOCELYN NG SHIN BUN of MSIG Date/Time: 16 Feb 2021 16:09

Estimated Cost: _____ Bill to: _____

OD: ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBJ 7050H Insured: FBB 9397Lat Workshop m/s Hua Chin (2000) Trading Motor Service Centre Tel: 68966619of 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit BatokPolicy No: MSD/VMT/20-418829-CA Claim No: MSC/V/21-000087

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 16-02-2021 4.53P.MPerson Contacted: MR LIMVehicle IN OUT

Date/Time	Action/Instruction (☒) Estimate
	FBJ 7050H- NS/INC20013560/T1td3q2 DOA :08/12/2020
	FBB 9397L- ☒
19/2/21	Submit PRS, repair range \$1,000-\$3,000 (3 days)