



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Date : 16/02/2021

TO: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Xiao Tang

Attn : Motor Claims Department
Fax : 6415 3727

Our Customer : Singapore Inkjet Infotech Pte

Vehicle No : GBG7366M

Model : Nissan NV200

Manufacture Year : 2017

Date of Accident : 13/02/2021

Total Estimate Repair Days : 7

Total Pages : 2

VSKYBAM2020148251

Re: Repair Estimate For Third Party Claim against SLR707H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front fender LH <i>Repair</i>	1	repair	repair	<i>x</i>
	Total			\$0.00	
	Less 30%			\$0.00	
	Sub Total 1			\$0.00	
B.	Spare Parts (Nett)				
1	Front bumper <i>Repld</i>	1	\$855.20	\$855.20	<i>589.70</i>
2	Front bumper side retainer LH <i>Repld</i>	1	\$96.80	\$96.80	<i>35.20</i>
3	Front bumper tow hook cover <i>Repld</i>	1	<i>28</i>	<i>28</i>	<i>✓</i>
4	Front bumper foam <i>Repld</i>	1	<i>358.90</i>	<i>358.90</i>	<i>291.60</i>
5	Front bumper reinforcement <i>Repld</i>	1	<i>756.90</i>	<i>756.90</i>	<i>614.50</i>
6	Engine under cover <i>Repld</i>	1	<i>250.30</i>	<i>250.30</i>	<i>x</i>
7	Fog lamp LH <i>Repld</i>	1	<i>258</i>	<i>258</i>	<i>✓</i>
8	Headlamp lower pad LH <i>Repld</i>	1	\$368.50	\$368.50	<i>✓</i>
9	Headlamp LH <i>Repld</i>	1	\$615.00	\$615.00	<i>✓</i>
	Total			\$1,935.50	
	Less 10%			\$193.55	
	Sub Total 2			\$1,741.95	
C.	Spare Parts (S/Nett)				
1	Front bumper clip <i>Repld</i>	10	\$5.00	\$50.00	<i>30</i>
2	Front fender inner shield clip <i>Repld</i>	8	\$5.00	\$40.00	<i>x</i>
3	Engine under cover clip <i>Repld</i>	10	\$5.00	\$50.00	<i>30</i>
4	Front number plate w/casing <i>Repld</i>	1	\$40.00	\$40.00	<i>x</i>
	Sub-Total 3			\$180.00	
	Total for Parts			\$1,921.95	
D.	Labour				
1	To check wiring.			\$60.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	<i>300</i>
3	Spray painting all affected parts & areas.			\$400.00	<i>300</i>
	Total Labour			\$860.00	
	Total Repair Cost			\$2,781.95	<i>630</i>



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
H/S 16/02/21
03 Days
Total: 3436.08
H/S: 2750 ✓