



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2104059

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 10/06/2021
Reference CC4/LPC21002219/Qba3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 2998J
Insured Veh. YN 7812H
Claim No. 20/21/21/VC05/024222
Policy No.
Accident Date 08/02/2021
Inspection Date 17/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21002219/Qba3q2 Date: 10/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7812H	Veh. Inspected	SLF 2998J	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024222	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	17/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA 1.5G	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NSP1707039693	Colour	BROWN	
Odometer	324564 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	FIRENZA	6 mm	
L/H Front Tyre	185/60 R15	FIRENZA	6 mm	
R/H Rear Tyre	185/60 R15	FIRENZA	6 mm	
L/H Rear Tyre	185/60 R15	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2021	Inspection Date	17/02/2021	
Survey held at	60 Jalan Lam Huat, #04-39/40 Carros Centre			
Repairer	LION CITY RENTALS PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2998J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	DEFORMED	900.00	679.00
1	FRONT BUMPER RH SIDE BRACKET	SERVICEABLE	90.00	-
1	FRONT BUMPER RH RETAINER	SERVICEABLE	120.00	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	380.00	-
1	FRONT BUMPER ENERGY ABSORBER	SERVICEABLE	120.00	-
1	FRONT GRILLE	SERVICEABLE	596.25	-
1	FRONT BONNET	DENTED	1,288.50	927.80
1	FRONT BONNET RUBBER SEAL	SERVICEABLE	45.00	-
1	FRONT BONNET LOCK	BENT	192.00	140.00
1	FRONT BONNET LOCK CATCH	SERVICEABLE	80.00	-
1	F/R HEADLAMP	SERVICEABLE	990.00	-
	LESS 25% DISCOUNT		-1,200.44	-436.70
			3,601.31	1,310.10
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	50.00	-
			130.00	30.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER ,SUPPORT PANEL ,FRONT BONNET OUT TO FACILITATE REPLACEMENT OF PARTS.		1,250.00	500.00
	TO RESPRAY FRONT BUMPER ,FRONT BONNET,BOTH FRONT FENDERS ,SUPPORT PANEL AND F/L WHEEL HOUSING .		900.00	400.00
			2,150.00	900.00
	GRAND TOTAL		5,881.31	2,240.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CC4/LPC21002219/Qba3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 2998J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 2998J

RE-INSPECTION

