



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0135/2021/KS
DATE : 15-Feb-21
WIP : 15428

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MALCOLM WONG WEE LEONG
ADDRESS : BLK 21 SELETAR ROAD
#02-59
SINGAPORE 807021
TELEPHONE : HP +65 91073391
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070123526
VEHICLE NO : **SLR 707 H**
MODEL CODE : AUDI A3 SPORTBACK 1.0 TFSI
MODEL YEAR : 25/8/2020
ENGINE NO : CHZ C38043
CHASSIS NO : WAUZZZ8V9LA033673
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Feb-21
PLACE OF ACCIDENT : NEAR 51 UBI AVE 3, SINGAPORE 408858
INFRONT OF AUTOBAC



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLR 707 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT AND REAR DOORS; MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$	700.00	✓
2	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLARS TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE RHS SEAT BELT AND HEAD AIRBAG.	S/N \$	1,800.00	✓ photo.
3	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$	800.00	✓ photo.
4	TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	✓ photo.
5	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OLD AND WELD RHS SILL PANEL AND RHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	3000 ✓
6	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, HINGES, DOOR ENTRANCES, RHS SILL PANEL AND RHS B-PILLAR. TO CARRY OUT JOINT SEALER WORKS AND CARRY OUT STONE CHIP TREATMENT	\$	4,500.00	2200 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 15,292.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 707 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	SECTIONAL PART - SIDE MEMBER <i>disassemble photo</i>	1	\$ 2,293.00	<i>bt</i> — 1834.40
2	REAR DOOR RH	1	\$ 2,767.00	<i>bt</i> — 2213.60
3	REAR DOOR OUTER SEAL RH	1	\$ 161.00	<i>na</i> — 128.40
4	BONDING AGENT	1	\$ 49.00	?
5	CLEANING SOLUTION	1	\$ 68.00	?
6	APPLICATOR	1	\$ 8.00	?
7	REAR DOOR ATTACHMENT PARTS RH	1	\$ 129.00	?
8	REAR DOOR CATCH RH	1	\$ 94.00	?
9	REAR DOOR SEAL, INNER RH	1	\$ 191.00	?
10	REAR DOOR WINDOW SLOT SEAL TRIM RH	1	\$ 270.00	X
11	REAR DOOR WINDOW GUIDE RH	1	\$ 420.00	?
12	REAR DOOR WINDOW REGULATOR RH	1	\$ 268.00	?
13	REAR DOOR LOCK RH	1	\$ 543.00	X
14	REAR DOOR PANEL RH	1	\$ 1,651.00	?
15	REAR DOOR HINGE RH - UPPER	1	\$ 44.00	?
16	REAR DOOR HINGE HALVE RH - UPPER	1	\$ 46.00	? <i>photo</i>
17	REAR DOOR HINGE RH - LOWER	1	\$ 47.00	<i>bt</i> — 37.60
18	REAR DOOR HINGE HALVE RH - LOWER	1	\$ 48.00	<i>bt - photo</i> 37.84
19	FRONT DOOR RH	1	\$ 2,767.00	<i>bt</i> — 2213.60
20	FRONT DOOR OUTER SEAL RH	1	\$ 68.00	<i>na</i> — 128.40
SUB TOTAL SPARE PARTS		:	\$ 11,932.00	

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 707 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	BONDING AGENT	1	\$	49.00	} X } m
22	CLEANING SOLUTION	1	\$	68.00	
23	APPLICATOR	1	\$	8.00	
24	FRONT DOOR ATTACHMENT PARTS RH	1	\$	241.00	
25	FRONT DOOR CATCH RH	1	\$	105.00	
26	FRONT DOOR DATA PLATE FOR TYRE PRESSURE	1	\$	30.00	net ✓ 24
27	ARYCLIX SEALANT	S/N	\$	180.00	net ✓
28	CAVITY WAX	S/N	\$	140.00	net ✓
29	METAL FILLER POWDER	S/N	\$	280.00	net ✓
30	STONE CHIP	S/N	\$	180.00	net ✓
31	SUNDRIES		\$	350.00	? net / 2850 28.40
TOTAL SPARE PARTS		:	\$	13,563.00	
TOTAL LABOUR CHARGES		:	\$	15,292.00	
GRAND TOTAL		:	\$	28,855.00	

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 97495745
16/2/21 @ 1145.
Ex: +bn Revent, Not Authorise.
P/P Resurvey before paint
taufik@lkkauto.com.
~~10 days~~ 11 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT