



Your Ref : 8029906900SG

Date: 23th March 2021

Our Ref : CS/AIG21002226/Bvf3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMW 5940D
INSURED VEHICLE: GBH 7538D
ACCIDENT ON 06/02/2021**

Instruction was received to inspect the vehicle Reg. No. SMW 5940D. The inspection was conducted on 17/02/2021 at the premises of M/s Lian Heng Painter Company, 160 Sin Ming Drive, #06-10 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:


Registration Number	: SMW 5940D
Make/Model	: Toyota Sienta 1.5G CVT Welcab Type I
Year of Registration	: 2020
Body Colour	: Silver
Chassis Number	: NSP1727009822
Engine Capacity	: 1496 cc

The vehicle sustained damages at the front, rear portion, o/s and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 90,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 51,770.00)
Nett Liability	<u>S\$ 38,230.00</u> =====

Vehicle Inspected By:



LIM TEOW GUAN
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.