

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21002236/UTF3E2

Date: 08/03/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBH1934H

Insured Vehicle No : GBG1126D

Date of Loss: 08/05/2020

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH1934H**

Make & Model: HONDA CB400, 399cc

Engine No: NC42E1124268

Reg. Date: 08/04/2013 (Man. Year: 2013)

Chassis No: JH2NC4298BK300447

Colour: Black

Odometer: 0 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17

Rear Tyre Size: 160/60Z R17

Front Left Side: Metzeler 6 mm

Rear Left Side: Metzeler 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,250.20	14,138.30	4,111.90	22.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,170.00	580.00	33.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	20,000.20	15,308.30	4,691.90	23.46

INSPECTION

Date of Assignment: 06/02/2021

Date Inspected: 17/02/2021 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$6,200.00
OMV :	\$7,215.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$1,909.00
COE Rebate (2) :	\$416.00
Total Rebate (1) + (2) = :	\$416.00

The total amount incurred will be Market Value \$6,200.00 minus Total Rebate \$416.00 = \$5,784.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Mar 2021)	
Parts:	N/A	HONDA CB400 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH1934H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	196.00 FL	*196.00 FL
2	1		*HEADLAMP	Cracked	420.00 FL	*420.00 FL
3	1		*HEADLAMP BRACKET	Twisted	72.00 FL	*72.00 FL
4	1		*HEADLAMP REAR BRACKET	Not Necessary	92.00 FL	*- FL
5	2		*FORK INNER TUBES	Bent	1,020.00 FL	*1,020.00 FL
6	2		*FORK OUTER TUBES	Bent / Cracked	1,040.00 FL	*1,040.00 FL
7	1		*FORK UNDER BRACKET	Bent	385.00 FL	*385.00 FL
8	1		*FORK UPPER BRACKET	Bent	285.00 FL	*285.00 FL
9	2		*FRONT BRAKE DISCS	Bent	1,120.00 FL	*1,120.00 FL
10	1		*FRONT RIM SHAFT	Bent	68.00 FL	*68.00 FL
11	1		*FRONT SPORT RIM	Bent	1,100.00 FL	*1,100.00 FL
12	1		*METER	Cracked	1,880.00 FL	*1,880.00 FL
13	1		*HANDLE-BAR	Bent	145.00 FL	*145.00 FL
14	1		*SET HANDLE-BAR END	Damaged	60.00 FL	*60.00 FL
15	1		*SET HAND-GRIP	Torn	80.00 FL	*80.00 FL
16	2		*SIDE MIRRORS	Broken	190.00 FL	*190.00 FL
17	1		*CLUTCH LEVER	Cracked	58.00 FL	*58.00 FL
18	1		*BRAKE LEVER	Not Necessary	72.00 FL	*- FL
19	2		*FRONT SIGNALS	Cracked	370.00 FL	*370.00 FL
20	1		*FUEL TANK	Dented	1,415.00 FL	*1,415.00 FL
21	1		*FRONT FOOTRESTS	N/S Cracked	150.00 FL	*75.00 FL
22	1		*FRONT FOOTREST BRACKET	N/S Bent	490.00 FL	*245.00 FL
23	1		*GEAR PEDAL	Serviceable	102.00 FL	*- FL
24	1		*REAR FOOTREST N/S	Broken	75.00 FL	*75.00 FL
25	1		*CLUTCH ENGINE COVER	Serviceable	680.00 FL	*- FL
26	1		*ENGINE BLOCK HOUSING	Repair	1,850.00 FL	*- FL
27	1		*RADIATOR	Distorted	650.00 FL	*650.00 FL
28	1		*RADIATOR SIDE COVER	Distorted	68.00 FL	*68.00 FL
29	2		*SIDE BOARDS	Cracked	280.00 FL	*280.00 FL
30	1		*SIDE STAND	Repair	90.00 FL	*- FL
31	1		*FRONT EXHAUST PIPE HEADER	Dented/ Bent	1,450.00 FL	*1,450.00 FL
32	1		*EXHAUST PIPE	Dented	1,800.00 FL	*1,800.00 FL
33	1		*EXHAUST PIPE PROTECTOR	Bent	105.00 FL	*105.00 FL
34	1		*REAR SIGNALS	N/S Cracked	190.00 FL	*95.00 FL
35	1		*REAR TAILBOARD	Repair	370.00 FL	*- FL
36	1		*SET NUMBER PLATE	Bent	28.00 FS	*20.00 FS
37	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
38	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
39	1		*SET STEERING CONE	Necessary	150.00 FS	*60.00 FS
40	1		*E.R.P.I.U	Serviceable	180.00 FS	*- FS
41	1		*REAR BOX	Cut	580.00 FS	*350.00 FS
42	1		*REAR BOX BRACKET	Distorted	100.00 FS	*100.00 FS
43	1		*ENGINE COVER GASKET	Not Necessary	50.00 FS	*- FS
44	3		*ENGINE OIL	Not Necessary	120.00 FS	*- FS
45	1		*SET ENGINE CRASH BAR	Bent	380.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	20,092.00	15,613.00
					- List Item Discount on L Items 10.00/10.00% (\$)	1,841.80	1,474.70
					Total Parts (\$)	18,250.20	14,138.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	70.00	70.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO RESPRAY PAINTING	New	500.00	400.00
4	TO REPAIR BODY FRAME	New	500.00	300.00
5	TO PROVIDE LABOUR	New	600.00	400.00
Gross Labour Cost (\$\$)			1,750.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >