

TP ALG.
Gulien.

SLS5720F. 2017 Sept.
Mercedes Benz C180 1595 cc.
WDD2050402R300728.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Front Bumper.	Defend	1510 ✓
Front Bumper Clips.	ME	50(SN). X
Front Bumper Side Holder LH.	ME	79. X
Front LH Wheel Rim	lit	1350 850(SN)
Front LH Lower Arm	Best	335 ✓
Front LH Knuckle Arm.	ME	1208 ✓
Front LH Wheel Hub c/w Bearing.	2nd	495 ✓
Front LH Shock Absorber.	ME	749 ✓
Headlamp LH	ME	3650 X
Front LH Tyre	ME	350(SN) X
Panel Beating.		400 250
Spray Painting.		400 250
Wiring.		50 30
To remove front bumper sensor		100 50
To remove front undercarriage.		380 180
To perform wheel alignment.		150 80

3,000

List: 2340
Len 10%: 2106
SN: 850
Labour: 810
Total: 3766
c/s: BIK
030mrs