

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF785S**AAD2102-070***Not Notified**11 Days @ 9750.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 FEB 2021**SHF785S**

VF1ABL15AUC283341

RENAULT

LATITUDE

15/02/2021

AIG

30/06/2016

	PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>B</i> 561.70	—
2	1 BUMPER LOWER REAR	\$	<i>MT</i> 411.90	—
3	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 16.60	—
4	1 BUMPER BRACKET CTR REAR	\$	<i>D11</i> 98.10	—
5	1 BUMPER BRACKET SIDE RH REAR	\$	<i>D11</i> 82.10	—
6	1 BUMPER RETAINER RH REAR	\$	<i>D11</i> 59.80	—
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>D11</i> 80.80	—
8	1 BUMPER RETAINER LH REAR	\$	<i>D11</i> 54.20	—
9	1 ABSORBER REAR	\$	<i>NIP</i> 217.30	X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 547.80	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 114.50	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 114.50	—
13	1 OUTER PANEL REAR (End Panel)	\$	<i>B</i> 745.80	—
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>W</i> 404.56	—
15	1 SPARE WHEEL PANEL	\$	<i>AT1A</i> 1,229.40	—
16	1 SPARE WHEEL PANEL BRACKET LH	\$	<i>R</i> 70.60	X
17	1 SPARE WHEEL PANEL BRACKET RH	\$	<i>R</i> 69.20	X
18	1 FUEL FLAP	\$	<i>W</i> 244.70	X
19	1 FENDER PANEL FRT RH	\$	<i>R</i> 437.10	X
20	1 FENDER PANEL FRT LH	\$	<i>R</i> 437.10	X
21	1 FENDER PANEL INNER REAR LH	\$	<i>R</i> 1,241.60	X
22	1 FENDER PANEL INNER REAR RH	\$	<i>R</i> 1,241.60	X
23	1 SPARE TYRE BOARD	\$	<i>SW</i> 680.90	X
24	1 FENDER INNER BOARD LH	\$	<i>SW</i> 561.40	X
25	1 FENDER INNER BOARD RH	\$	<i>SW</i> 561.40	X
26	1 WHEEL HOUSE PRE ASSY LH (CENTER)	\$	<i>R</i> 1,241.60	X
27	1 WHEEL HOUSE PRE ASSY RH (CENTER)	\$	<i>R</i> 1,241.60	X
28	1 SILL PANEL OUTER LH	\$	<i>B</i> (N.C.) 1,902.00	X

Trans-cab Auto Services Pte Ltd

AAD2102-070

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF785S

29	1 SILL PANEL INNER LH	\$	nc	A	483.20	X
30	1 SILL PANEL OUTER RH	\$	nc	H	1,856.50	X
31	1 SILL PANEL INNER RH	\$	nc	H	371.10	X
32	1 TAILLAMP LH	\$		CM	401.40	✓
33	1 TAILLAMP RH	\$		CM	401.40	✓
34	1 EXHAUST REAR	\$		R	5,263.60	X
35	1 EXHAUST BRACKET REAR	\$		Sm	24.80	X
36	1 EXHAUST CAP REAR	\$		Re	125.40	✓
37	1 BOOT REAR	\$		Re	1,677.20	✓
38	1 BOOT BADGE 'RENAULT'	\$		Re	82.40	✓
39	1 BOOT BADGE	\$		Re	95.80	✓
40	1 BOOT REFLECTOR LAMP LH	\$		CM	277.70	✓
41	1 BOOT REFLECTOR LAMP RH	\$		CM	277.70	✓
42	1 BUMPER REFLECTOR LH	\$		Re	16.60	X
43	1 BUMPER REFLECTOR RH	\$		CM	16.60	✓
44	1 BOOT HINGE LH	\$		Re	254.20	✓
45	1 BOOT HINGE RH	\$		Re	254.20	✓
46	1 BOOT STRUT LH	\$		Re	145.10	X
47	1 BOOT STRUT RH	\$		Re	145.10	X
48	1 BOOT LOCK LINKAGE	\$		Re	20.60	X
49	1 BOOT LOCK LINKAGE HOLDER	\$		Re	99.50	X
50	1 BOOT LOCK	\$		Re	246.60	✓
51	1 BOOT LOCK CATCH	\$		R	41.70	X
52	1 BOOT FINISHER	\$		SVC	344.70	X
		\$			27,592.96	
		10% \$			2,759.30	
		\$			<u>24,833.66</u>	

Special Nett

1	1SET PARKING AID	\$	Short	700.00	400.00
2	1SET REAR BUMPER CLIP	\$	Re	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BONNET LOCK NUT	\$	nn	60.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	Re	66.00	✓

Trans-cab Auto Services Pte Ltd

AAD2102-070

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF785S

10	1	EXHAUST MOUNTING REAR	\$	17.82	X
11	1	REAR BOOT STICKER 'Trans-cab'	\$	80.00	305N
12	1	REAR BOOT STICKER '6555-3333'	\$	80.00	305N
13	1	BUMPER CLIP FRT	\$	85.00	X
14	1	BUMPER RETAINER CLIP FRT	\$	70.00	X
15	1	BUMPER GRILLE LOWER CLIP	\$	70.00	X
16	1	BUMPER FOG LAMP GRILLE CLIP	\$	65.00	X
17	1	LICENSE PLATE WITH HOLDER FRT	\$	120.00	X
18	2	WINDSCREEN SEALANT	\$	150.00	405N
19	1	WINDSCREEN MOULDING	\$	200.00	X
20	1	WINDSCREEN INNER SPONGE SEAL	\$	130.00	305N
TOTAL			\$	1,572.82	
TOTAL PARTS			\$	26,406.48	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	13201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	20001
To Rust-Proofing Of The Affected Areas.	\$	170.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} 601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	1201

Trans-cab Auto Services Pte Ltd

AAD2102-070

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF785S

To transfer of rear windscreen fittings and conduct
water seepage test. \$ 170.00 1201

To check steering geometry and computer wheel
alignment \$ 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 201

TOTAL \$ 7,580.00

Over All Total \$ 58,820.15

(LUMP SUM)

Repair Days

20 DAYS

16 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: