

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R**AAD2102-068***Not Authored
Subway B&point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 FEB 2021**SHD5512R**

JTDKB3FU303076924

TOYOTA

PRIUS

15/02/2021

AIG

22/11/2018

PART**LIST**

1	COVER, REAR BUMPER	\$	<i>R</i>	442.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i>	332.70	✓
1	COVER, REAR BUMPER, LOWER	\$	<i>MR</i>	15.40	✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>R</i>	576.30	✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>mgcm</i>	116.50	✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>mgcm</i>	117.70	✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	<i>CM</i>	123.70	✓
1	FILLER, REAR BUMPER EXTENSION, LH	\$	<i>CM</i>	123.70	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>R</i>	1,147.80	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>CM</i>	925.60	✓
1	COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i>	64.50	X
1	COVER, REAR COMBINATION LAMP, LH	\$	<i>SL</i>	64.50	X
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>mgcm</i>	259.20	✓
1	WEATHERSTRIP, BACK DOOR	\$	<i>DI/110</i>	372.30	✓
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>SL</i>	56.50	X
1	BOARD, BACK DOOR TRIM	\$	<i>Removal</i>	225.20	X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	<i>CM</i>	443.30	✓
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	<i>CM</i>	451.80	✓
1	LENS AND BODY, REAR LAMP, LH	\$	<i>SL</i>	502.00	✓
1	LENS AND BODY, REAR LAMP, RH	\$	<i>SL</i>	502.00	✓
1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>SL</i>	355.90	X
1	BOX, DECK FLOOR, RH	\$	<i>SL</i>	313.60	X
1	BOX, DECK FLOOR, LH	\$	<i>SL</i>	313.00	X
1	BOARD, REAR FLOOR, NO.1	\$	<i>SL</i>	519.00	X
1	COVER ASSY, TONNEAU	\$	<i>SL</i>	979.40	X
1	BOX, DECK FLOOR, REAR	\$	<i>SL</i>	105.80	X
1	PANEL ASSY, DECK TRIM SIDE, LH	\$	SVC	355.90	X
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>SL</i>	56.50	X

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

1 DUCT ASSY, QUARTER VENT, RH	\$	SH	67.00	X
1 PANEL SUB-ASSY, QUARTER, RH	\$	N	871.50	X
1 LINER, REAR WHEEL HOUSE, RH	\$	SH	139.80	X
1 SEAL, REAR BUMPER SIDE, RH	\$	SH	88.50	X
1 TROUGH, BACK DOOR OPENING, LH	\$	SH	103.40	X
1 TROUGH, BACK DOOR OPENING, RH	\$	SH	103.40	X
1 COVER, FLOOR UNDER, NO.1	\$	SH	175.10	X
1 COVER, FLOOR UNDER, NO.2	\$	SH	241.90	X
1 COVER, REAR FLOOR	\$	SH	229.90	✓
1 COVER, DECK TRIM, REAR	\$	SH	126.70	X
1 PAN, REAR FLOOR	\$	N	583.40	X
1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	N	196.50	X
1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	SH	78.30	X
1 INSULATOR, MAIN MUFFLER HEAT, RH	\$	SH	141.00	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	N	651.00	X
1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	N	467.00	X
1 SWITCH ASSY, BACK DOOR OPENER	\$	SH	179.10	X
1 COVER, BACK DOOR LOCK	\$	N	30.20	X
1 SEAL, REAR BUMPER SIDE, LH	\$	SH	88.50	X
1 PANEL SUB-ASSY, QUARTER, LH	\$	N	871.50	X
1 LINER, REAR WHEEL HOUSE, LH	\$	SH	139.80	X
1 DUCT ASSY, QUARTER VENT, LH	\$	SH	67.00	X
1 SPOILER, SUB ASSY, REAR	\$	N	1,575.40	X
1 SEAL, REAR SPOILER	\$	N	16.70	✓
1 PROTECTOR, REAR SPOILER, NO.4	\$	SH	16.70	X
1 PROTECTOR, REAR SPOILER, NO.3	\$	SH	16.70	X
1 PROTECTOR, REAR SPOILER, NO.1	\$	SH	16.70	X
1 LAMP SET, STOP CENTER	\$	SH	192.30	✓
1 LAMP SUB-ASSY, LICENSE PLATE	\$	SH	287.80	X
1 GLASS, BACK WINDOW FIX	\$	Shattered	761.40	✓
1 MOULDING, BACK WINDOW, LOWER NO.2	\$	N	23.60	✓
1 MOULDING, BACK WINDOW, OUTSIDE LH NO.2	\$	N	30.90	✓
1 MOULDING, BACK WINDOW, OUTSIDE RH NO.2	\$	N	30.90	✓
1 DAM, BACK DOOR GLASS ADHESIVE, NO.2	\$	N	28.90	✓
1 WIRE, LUGGAGE ROOM, NO.3	\$	SH	170.70	X
1 WIRE, BACK DOOR, NO.2	\$	SH	294.40	X
1 WIRE, BACK DOOR, NO.1	\$	SH	247.40	X

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

1	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, LH	\$	P _L	63.30	X
1	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, RH	\$	S _L	63.30	X
1	STAY ASSY, BACK DOOR, LH	\$	P _L	242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	S _L	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	N	61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	N	61.00	X
1	HANDLE, DOOR PULL	\$	M ₁	23.40	✓
1	COVER, FRONT BUMPER	\$	B ₁	516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	D ₁	103.40	✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R ₁	716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	D ₁	246.10	✓
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM	132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	SVC	79.60	X
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	OR	80.10	X
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	D ₁	82.30	✓
1	COVER, ENGINE UNDER, NO.1	\$	SVC	472.40	X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	SVC	241.90	X
1	EXTENSION, FRONT BUMPER, RH	\$	P _L	120.10	X
1	EXTENSION, FRONT BUMPER, LH	\$	S _L	120.10	✓
1	COVER, FRONT BUMPER HOLE, LH	\$	CM	29.30	✓
1	COVER, FRONT BUMPER HOLE, RH	\$	N	29.30	✓
1	LAMP ASSY, FOG, LH	\$	P _L	951.40	X
1	LAMP ASSY, FOG, RH	\$	P _R	951.40	X
1	UNIT ASSY, HEADLAMP, LH	\$	M ₃ B ₂	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	SVC	960.50	X
1	UNIT ASSY, HEADLAMP, RH	\$	CM	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	SVC	960.50	X
1	MOTOR, HEADLAMP LEVELING, RH	\$	P _L	487.50	X
1	GRILLE SUB-ASSY, RADIATOR	\$	CM	346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	D ₁	170.10	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	N	90.80	✓
1	FENDER SUB-ASSY, FRONT LH	\$	B ₁	977.80	✓
1	LINER, FRONT FENDER, LH	\$	P _L	202.50	X
1	EMBLEM, SIDE PANEL	\$	N	54.60	✓
1	SUPPORT, RADIATOR, UPPER RH	\$	SVC	78.90	X
1	SUPPORT, RADIATOR, UPPER LH	\$	SVC	78.90	X
1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	B ₁	377.10	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2102-068**SHD5512R**

1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	SVC	409.90	X
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	SVC	245.10	X
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	SVC	245.10	X
1	HOOD SUB-ASSY	\$	Ben	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	Dir	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	Dir	58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	Ben	78.30	✓
1	INSULATOR, HOOD	\$	Return	410.90	✓
1	LOCK ASSY, HOOD	\$	Dir	135.00	✓
1	CABLE ASSY, HOOD LOCK CONTROL	\$	SVC	54.90	X
1	SUPPORT ASSY, HOOD	\$	Sn	44.20	X
1	SEAL, HOOD TO FRONT END PANEL	\$	Sn	51.60	X
1	WIRE, ENGINE ROOM MAIN	\$	Sn	7,323.90	X
1	HORN ASSY, HIGH PITCHED	\$	SVC	134.80	X
1	HORN ASSY, LOW PITCHED	\$	SVC	134.80	X
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	Sn	69.90	X
1	GUIDE, RADIATOR AIR, NO.1 RH	\$	Sn	65.30	X
1	GUIDE, RADIATOR AIR, NO.3	\$	Sn	112.70	X
1	GUIDE, RADIATOR AIR, NO.2	\$	Sn	53.40	X
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$	Sn	32.40	X
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$	Sn	32.60	X
1	INLET, AIR CLEANER, NO.1	\$	Sn	155.60	X
1	INLET, AIR CLEANER, NO.3	\$	Sn	42.10	X
1	INLET, AIR CLEANER, NO.2	\$	Sn	112.70	X
1	HOSE, AIR CLEANER, NO.1	\$	Sn	74.00	X
1	JAR ASSY, WINDSHIELD WASHER	\$	SVC	219.10	X
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	Sn	292.40	X
1	INLET SUB-ASSY, WASHER	\$	Sn	67.00	X
1	CONDENSER ASSY, COOLER	\$	SVC	1,783.20	X
1	HOSE SUB-ASSY, SUCTION	\$	SVC	646.80	X
1	HOSE SUB-ASSY, DISCHARGE	\$	SVC	402.90	X
1	PIPE SUB-ASSY, SUCTION	\$	SVC	465.80	X
1	SENSOR, AIRCONDITIONER PRESSURE	\$	SVC	342.80	X
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	SVC	691.00	X
1	COMPRESSOR ASSY, W/MOTOR	\$	Sn	4,771.60	X
1	RADIATOR ASSY	\$	SVC	2,218.00	X
1	SHROUD, FAN	\$	SVC	264.70	X

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

1 FAN, RH	\$	SVC	281.30	X
1 FAN, LH	\$	SVC	219.10	X
1 MOTOR, COOLING FAN, LH	\$	SVC	655.10	X
1 MOTOR, COOLING FAN, RH	\$	SVC	535.50	X
1 TANK ASSY, INVERTER RESERVE	\$	Ln	443.00	X
1 INVERTER WATER PUMP ASSY(W/MOTOR)	\$	Ln	518.60	X
1 BATTERY	\$	SVC	1,584.90	X
1 CLAMP, BATTERY, NO.2	\$	Ln	51.80	X
1 CLAMP SUB-ASSY, BATTERY	\$	Ln	115.50	X
1 TERMINAL, BATTERY POSITIVE	\$	Ln	58.10	X
1 COVER, FUSIBLE LINK	\$	Ln	33.90	X
1 SENSOR ASSY, BATTERY STATE	\$	Ln	306.10	X
1 BLOCK ASSY, FUSIBLE LINK	\$	Ln	119.60	X
1 TANK, RESERVE SEALED W/O CAP	\$	Ln	151.40	X
1 CLEANER ASSY, AIR	\$	CRT	1,147.00	✓
1 BRACKET, HEADLAMP, LH	\$	Ln	34.80	X
1 BRACKET, HEADLAMP, RH	\$	Ln	34.80	X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	Ln	47.50	X
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$	Ln	47.50	X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	Ln	59.30	X
1 BRACKET, FRONT BUMPER SIDE, RH	\$	Ln	59.30	X
1 BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	Ln	36.60	X
1 BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	Ln	36.60	X
1 MEMBER SUB-ASSY, FRONT SIDE, RH	\$	Ln	2,342.30	X
1 COVER, RADIATOR SUPPORT OPENING	\$	Ln	235.30	X
1 THERMISTOR ASSY	\$	Ln	80.90	X
1 MEMBER SUB-ASSY, SIDE, REAR RH	\$	Ln	288.50	X
1 ACTUATOR ASSY, SHIFT CONTROL	\$	Ln	1,036.40	X
1 COOLER, MOTOR COOLING	\$	Ln	297.20	X
TOTAL	\$		69,046.80	
25%	\$		17,261.70	
	\$		51,785.10	

Special Nett

1SET PARKING AID	\$	short	700.00	2201n
1SET REAR BUMPER CLIP	\$	new	95.00	681n
2 WINDSCREEN SEALANT	\$	new	150.00	801n

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2102-068

SHD5512R

1 WINDSCREEN MOULDING	\$	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	30sn
1 REAR TAILGATE TOYOTA LOGO	\$	47.90	—
1 REAR TAILGATE WORDING 'PRIUS'	\$	54.60	—
1 REAR TAILGATE WORDING 'HYBRID'	\$	54.60	—
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00	30sn
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00	30sn
1 REAR BUMPER PROTECTOR	\$	180.00	X
2 SEAM SEALANT	\$	250.00	X
1SET REAR FENDER LINER CLIP	\$	85.00	X
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1 REAR NUMBER PLATE WITH HOLDER	\$	140.00	45sn
1SET TAILLAMP LOWER CLIP	\$	55.00	X
1SET TAILLAMP UPPER CLIP	\$	55.00	X
1 END PANEL TRIM CLIP	\$	65.00	—
1 REAR SPOILER CLIP	\$	70.00	X
1SET BUMPER CLIP FRNT	\$	95.00	60sn
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00	45sn
1SET CLIP, FRONT FENDER LINER	\$	85.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	85.00	X
4L Radiator Coolant	\$	120.00	30sn
1 HOOD INSULATOR CLIP	\$	55.00	X
1 Engine Under Cover Clip	\$	60.00	X
TOTAL	\$	3,277.10	

TOTAL PARTS	\$	55,062.20
--------------------	-----------	------------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	300.00	1800
----	--------	------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	1000
----	--------	------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,200.00	14000
----	----------	-------

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$		180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	NN	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	NN	380.00	401 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	NN	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	901
Towing Fees	\$		150.00	501
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	19801
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	401
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	220.00	X
To replace, refix and top up coolant for radiator	\$		170.00	501

Trans-cab Auto Services Pte Ltd

AAD2102-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

To lift-up / out engine with gear box and refit. \$ *nn* 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair. \$ *nn* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators. \$ *nn* 380.00 X

TOTAL \$ 10,290.00

Over All Total \$ 65,352.20

(PART-BY-PART) Repair Days ~~25~~ DAYS

11 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: