

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5982Y

AAD2102-059

*Not Authorised
L/Sing & 6450/p*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

16 FEB 2021

SHC5982Y
VF1ABL15AUC280993
RENAULT
LATITUDE
11/02/2021
CHINA
18/12/2014

PART

LIST

QTY	PART	UNIT	PRICE	TOTAL	STATUS
1	1 REAR BOOT	\$	<i>Bz</i> 1,677.20	1,677.20	✓
2	1 BOOT FINISHER	\$	<i>Sm</i> 344.70	344.70	X
3	1 BOOT STRUT LH	\$	<i>Sm</i> 145.10	145.10	X
4	1 BOOT STRUT RH	\$	<i>Sm</i> 145.10	145.10	X
5	1 BOOT WEATHERSTRIP	\$	<i>89.105W</i> <i>Wm</i> 178.20	178.20	<i>50Wm</i>
6	1 BOOT HINGE LH	\$	<i>R</i> 254.20	254.20	X
7	1 BOOT HINGE RH	\$	<i>R</i> 254.20	254.20	X
8	1 BOOT BADGE 'RENAULT'	\$	<i>Me</i> 82.40	82.40	✓
9	1 BOOT BADGE	\$	<i>Me</i> 95.80	95.80	✓
10	1 BOOT LOCK	\$	<i>R</i> 246.60	246.60	X
11	1 BOOT REFLECTOR LAMP LH	\$	<i>Wd</i> 277.70	277.70	✓
12	1 BOOT REFLECTOR LAMP RH	\$	<i>Wd</i> 277.70	277.70	✓
13	1 BUMPER COVER REAR	\$	<i>Bz</i> 561.70	561.70	✓
14	1 BUMPER LOWER REAR	\$	<i>Bz</i> 411.90	411.90	✓
15	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 16.60	16.60	✓
16	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 16.60	16.60	X
17	1 BUMPER BRACKET CTR REAR	\$	<i>Dit</i> 98.10	98.10	✓
18	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 82.10	82.10	X
19	1 BUMPER RETAINER RH REAR	\$	<i>Sm</i> 59.80	59.80	X
20	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 80.80	80.80	X
21	1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 54.20	54.20	X
22	1 BUMPER BEAM REAR	\$	<i>Bz</i> 547.80	547.80	✓
23	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Bz</i> 114.50	114.50	✓
24	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bz</i> 114.50	114.50	✓
25	1 OUTER PANEL REAR (End Panel)	\$	<i>Bz</i> 745.80	745.80	✓
26	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Wd</i> 404.56	404.56	✓
27	1 FENDER PANEL REAR LH	\$	<i>R</i> 1,933.20	1,933.20	X

Trans-cab Auto Services Pte Ltd

AAD2102-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5982Y

28	1 WHEELARCH REAR LH	\$	<i>Sm</i> 275.40	X
29	1 TAILLAMP LH	\$	<i>mg cmf</i> 401.40	✓
30	1 TAILLAMP RH	\$	<i>s s</i> 401.40	✓
		\$	10,299.26	
		10% \$	1,029.93	
		\$	9,269.33	

Special Nett

1	1SET PARKING AID	\$	<i>Nullshot</i> 700.00	<i>400sm</i>
2	1SET FENDER CLIP	\$	<i>na</i> 65.00	X
3	1SET FENDER LINER CLIP	\$	<i>na</i> 60.00	X
4	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	✓
5	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	X
6	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
7	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	X
8	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
9	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00	X
10	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	✓
11	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i> 17.82	} X
12	1 BUMPER CLIP FRT	\$	<i>Sm</i> 85.00	
13	1 BUMPER RETAINER CLIP FRT	\$	<i>Sm</i> 70.00	
14	1 BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 70.00	
15	1 LICENSE PLATE WITH HOLDER FRT	\$	<i>Sm</i> 120.00	
16	2 WINDSCREEN SEALANT	\$	<i>na</i> 150.00	
17	1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00	
18	1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00	
TOTAL		\$	1,412.82	
TOTAL PARTS		\$	10,682.15	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 300.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>8801</i>

Trans-cab Auto Services Pte Ltd

AAD2102-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5982Y

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>Foot</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>bol</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>bol</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>bol</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>bol</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>bol</i>

TOTAL \$ 7,880.00**Over All Total \$ 27,831.49****(LUMP SUM)****Repair Days****20 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: