

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/p 91082728

Wen Huijun
468 Sims Ave
#03-10
Singapore 387544

Vehicle No : SKP 9375 U
Make : Volkwagon Golf
Year : 2014

Not Authorized
L1 Rep @ 3600h
Running After Paint
4 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	1450	
2 pcs	Rear tail-gate reflector		
1 pc	Rear tail-gate emblem " Golf "		
1 pc	Rear tail-gate emblem " Tsi "		
1 pc	Rear tail-gate inner trim board	? ? 310.00	
1 pc	Rear tail-gate inner lock		
2 pcs	Rear tail-lamp		
1 pc	Rear boot rubber		
2 pcs	Rear no plate lamp		
1 pc	Rear end panel		
1 pc	Rear end panel inner garnish		
2 pcs	Rear fender inner trim board		
1 pc	Rear bumper		
1 pc	Rear bumper lower garnish		
1 pc	Rear bumper reinforcement		
2 pcs	Rear bumper side retainer		
2 pcs	Rear bumper bracket		
2 pcs	Rear bumper reflector		
1 pc	Rear exhaust silencer		
1 pc	Rear tail-gate glass moulding		

Bt	\$1,475.60	✓
Sm	\$610.20	X
mm	\$88.00	✓
mm	\$85.00	✓
my	\$356.00	X
mm	\$145.00	✓
Sm	\$970.20	X
Sm	\$228.00	X
Sm	\$76.00	X
R	\$475.00	X
Sm	\$115.00	X
Sm	\$1,100.20	X
Bm	\$905.10	✓
mm	\$285.00	✓
R	\$357.00	X
Sm	\$136.00	X
Sm	\$160.00	X
Sm	\$216.00	X
R	\$765.00	X
mm	\$75.00	X
	\$8,623.30	
Less 10 %	\$862.33	
	\$7,760.97	

S. Nett Item

1 pc	Rear windscreen sealant
1 pc	Rear reverse sensor
15 pcs	Bumper clip
1 pcs	Badge and sticker

1 pc No plate - 400\$ LPS DD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: DD

mm	\$55.00	400\$
Short	\$200.00	2
mm	\$30.00	✓
mm	\$150.00	200\$
	\$435.00	

balance c/f \$8,195.97

SKP 9375 U

balance b/f \$8,195.97

Labour Charges

Remove/renew the above parts. Cut out & reweld rear end panel, knock out & reshape rear boot floor panel etc.

\$1,000.00 *400l*

To putty and spray paint.

\$1,000.00 *600l*

Check/reconnect wiring.

\$45.00 *20l*

To spray anti rust on accident affected portion.

\$120.00 *30l*

Remove/renew rear windscreen glass

\$120.00 *✓*

Remove/refit rear boot lid lock mechanism, inner trim to new lid..

\$100.00 *60l*

Remove/renew exhaust silencer

nn \$150.00 *x*

Total \$10,730.97