

ASS. REQ. BY:

REF:

ASM/21002244/kg

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

S1M03316

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

845k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP 93754 Yr Regn: 10, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf c.c. 1395

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

111511

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW ZZZ AU ZEW 41631P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

4/2/01

D.O.I.

23/2/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/3 11.20 83600 Collision U/C 7130-97, 66%

11/3/21 @ 3.18p revised to Eugene Chiu via Smart Claims.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trlp:

2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Smart Claims - TP

Lump Sum / I.B.I. (\$

3600

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Singapore NRIC                       |
| Owner ID:                           | 516Z                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SKP9375U                             |
| Vehicle to be Exported:             | Yes                                  |
| Intended Deregistration Date:       | 24 Feb 2021                          |
| Vehicle Make:                       | VOLKSWAGEN                           |
| Vehicle Model:                      | GOLF A7 1.4 TSI AT 5G13GZ W/O HID    |
| Primary Colour:                     | White                                |
| Manufacturing Year:                 | 2014                                 |
| Engine No.:                         | CXS202358                            |
| Chassis No.:                        | WVWZZZAUZEW416319                    |
| Maximum Power Output:               | 90.0 kW (120 bhp)                    |
| Open Market Value:                  | \$19,226.00                          |
| Original Registration Date:         | 23 Oct 2014                          |
| First Registration Date:            | 23 Oct 2014                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$5,000.00                           |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 22 Oct 2024                          |
| PARF Rebate Amount:                 | \$3,250.00                           |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 22 Oct 2024                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 10                                   |
| QP Paid:                            | \$63,880.00                          |
| COE Rebate Amount:                  | \$23,374.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$26,624.00</b>                   |

The information contained herein is correct as at 23 Feb 2021

OK



# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Wen Huijun  
468 Sims Ave  
#03-10  
Singapore 387544

Vehicle No : SKP 9375 U  
Make : Volkwagon Golf  
Year : 2014

*Not Authorized*  
*L1 Rep @ 3600h*  
*Running After Paint*  
*4 days*

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

## Estimate Cost Of Repair

|       |                                 |            |  |
|-------|---------------------------------|------------|--|
| 1 pc  | Rear tail-gate assy             | 1450       |  |
| 2 pcs | Rear tail-gate reflector        |            |  |
| 1 pc  | Rear tail-gate emblem " Golf "  |            |  |
| 1 pc  | Rear tail-gate emblem " Tsi "   |            |  |
| 1 pc  | Rear tail-gate inner trim board | ? ? 310.00 |  |
| 1 pc  | Rear tail-gate inner lock       |            |  |
| 2 pcs | Rear tail-lamp                  |            |  |
| 1 pc  | Rear boot rubber                |            |  |
| 2 pcs | Rear no plate lamp              |            |  |
| 1 pc  | Rear end panel                  |            |  |
| 1 pc  | Rear end panel inner garnish    |            |  |
| 2 pcs | Rear fender inner trim board    |            |  |
| 1 pc  | Rear bumper                     |            |  |
| 1 pc  | Rear bumper lower garnish       |            |  |
| 1 pc  | Rear bumper reinforcement       |            |  |
| 2 pcs | Rear bumper side retainer       |            |  |
| 2 pcs | Rear bumper bracket             |            |  |
| 2 pcs | Rear bumper reflector           |            |  |
| 1 pc  | Rear exhaust silencer           |            |  |
| 1 pc  | Rear tail-gate glass moulding   |            |  |

|           |            |   |
|-----------|------------|---|
| Bt        | \$1,475.60 | ✓ |
| Sm        | \$610.20   | X |
| mm        | \$88.00    | ✓ |
| mm        | \$85.00    | ✓ |
| my        | \$356.00   | X |
| mm        | \$145.00   | ✓ |
| Sm        | \$970.20   | X |
| Sm        | \$228.00   | X |
| Sm        | \$76.00    | X |
| R         | \$475.00   | X |
| Sm        | \$115.00   | X |
| Sm        | \$1,100.20 | X |
| Bm        | \$905.10   | ✓ |
| mm        | \$285.00   | ✓ |
| R         | \$357.00   | X |
| Sm        | \$136.00   | X |
| Sm        | \$160.00   | X |
| Sm        | \$216.00   | X |
| R         | \$765.00   | X |
| mm        | \$75.00    | X |
|           | \$8,623.30 |   |
| Less 10 % | \$862.33   |   |
|           | \$7,760.97 |   |

## S. Nett Item

|        |                         |
|--------|-------------------------|
| 1 pc   | Rear windscreen sealant |
| 1 pc   | Rear reverse sensor     |
| 15 pcs | Bumper clip             |
| 1 pcs  | Badge and sticker       |

1 pc No plate - 400\$ LPS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

|       |          |       |
|-------|----------|-------|
| mm    | \$55.00  | 400\$ |
| Short | \$200.00 | ✓     |
| mm    | \$30.00  | ✓     |
| mm    | \$150.00 | 200\$ |
|       | \$435.00 |       |

balance c/f \$8,195.97

SKP 9375 U

balance b/f \$8,195.97

Labour Charges

Remove/renew the above parts. Cut out & reweld rear end panel, knock out & reshape rear boot floor panel etc.

\$1,000.00 *400*

To putty and spray paint.

\$1,000.00 *600*

Check/reconnect wiring.

\$45.00 *20*

To spray anti rust on accident affected portion.

\$120.00 *30*

Remove/renew rear windscreen glass

\$120.00 *✓*

Remove/refit rear boot lid lock mechanism, inner trim to new lid..

\$100.00 *60*

Remove/renew exhaust silencer

*nn* \$150.00 *x*

Total \$10,730.97