

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 23 Feb 2021

Preliminary Advice

Vehicle No	: SKU977R	Accident Date	: 10/02/2021
Make	: HYUNDAI VELOSTER	Policy No.	: D20MPC0006416
Assignment Date	: 17/02/2021	Excess	: S\$0.00
Date of Inspection	: 19/02/2021	Est. Duration of Repair	: 5
Inspection At	: 56 LOYANG WAY #04-04		
	REPAIRER : AP AUTOMOTIVE SERVICES PTE LTD (HQ)		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,170.00
Revised Amount	:S\$	6,400.00
Check Items (Estimated)	:S\$	500.00
Total	:S\$	6,900.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	41,812.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,188.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING FOR PARTS PRICES.