



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8425U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILLAMP LH	SERVICEABLE	365.00	-
1	TAILLAMP RH	SERVICEABLE	365.00	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	248.00	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	248.00	-
1	REAR END PANEL	BENT	595.00	595.00
1	SPARE WHEEL CARRIER	BENT	285.50	285.50
1	REAR SWING DOOR LH	TO REPAIR SEE LABOUR	1,650.00	-
1	REAR SWING DOOR RH	BENT	1,650.00	1,650.00
1	REAR SWING DOOR HINGE LH (TOP)	TO REPAIR SEE LABOUR	148.60	-
1	REAR SWING DOOR HINGE LH (LOWER)	TO REPAIR SEE LABOUR	148.60	-
1	REAR SWING DOOR HINGE RH (TOP)	TO REPAIR SEE LABOUR	148.60	-
1	REAR SWING DOOR HINGE RH (LOWER)	TO REPAIR SEE LABOUR	148.60	-
1	REAR SWING DOOR LEDGE HOLDER BAR LH	TO REPAIR SEE LABOUR	280.20	-
1	REAR SWING DOOR LEDGE HOLDER BAR RH	BENT	280.20	280.20
1	REAR SWING DOOR STICKER "70"	NOT NECESSARY	15.00	-
1	REAR CARGO ALUMINIUM	TO REPAIR SEE LABOUR	1,450.00	-
1	REAR NUMBER PLATE LAMP	SERVICEABLE	180.50	-
1	REAR NUMBER PLATE PANEL	TO REPAIR SEE LABOUR	205.10	-
	LESS 10% DISCOUNT		-	-281.07
			8,411.90	2,529.63
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	40.00	15.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
			340.00	15.00

Report Ref No. CS/AGI21002255/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL LH,TAILLAMP PANEL RH,REAR SWING DOOR LH,REAR SWING DOOR HINGE LH (TOP),REAR SWING DOOR HINGE LH (LOWER),REAR SWING DOOR HINGE RH (TOP),REAR SWING DOOR HINGE RH (LOWER),REAR SWING DOOR LEDGE HOLDER BAR LH,REAR CARGO ALUMINIUM AND REAR NUMBER PLATE PANEL.		1,500.00	900.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT PEARL WHITE ON THE AFFECTED PORTION.		900.00	200.00
	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL.		120.00	30.00
	TO CHECK WIRING FUNCTIONS.		80.00	15.00
			2,600.00	1,145.00
GRAND TOTAL			11,351.90	3,689.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/AGI21002255/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.