

2/17/2021

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/02/2021
Vehicle Reg. No.:	SKT7977A	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	KIA FORTE K3, 1.6 SX S/R HID (A)	Vehicle Reg. Date:	24/06/2015
Vehicle Colour:	GREY		
Engine No:	G4FGFH770876	Chassis No:	KNAFZ411MF5417252
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	4,425.30
Miscellaneous Items	11.00
Labour	1,620.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,056.30
+ GST 7.00% (S\$)	423.94
Nett Amount (S\$)	6,480.24

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 Feb 2021)

Parts: 143 **KIA FORTE K3 1.6 SX S/R HID (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT7977A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the **END OF ESTIMATES** marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>St</i>	10.00	0.00	*1,365.00 FL
2	1		*REAR BOOT LOGO <i>re</i>	10.00	0.00	*82.00 FL
3	1		*REAR BOOT EMBLEM FORTE <i>re</i>	10.00	0.00	*86.00 FL
4	1		*REAR BOOT EMBLEM K3 <i>re</i>	10.00	0.00	*75.00 FL
5	1		*REAR BOOT EMBLEM C&C <i>re</i>	10.00	0.00	*40.00 FL
6	1		*REAR BOOT LOCK <i>X</i>	10.00	0.00	*100.00 FL
7	2		*REAR BOOT HINGE L+R <i>X</i>	10.00	0.00	*130.00 FL
8	1		*REAR BOOT RUBBER <i>re</i>	10.00	0.00	*98.00 FL
9	1		*REAR PANEL <i>St</i>	10.00	0.00	*291.00 FL
10	1		*REAR PANEL TRIM <i>?</i>	10.00	0.00	*95.00 FL
11	6		*REAR PANEL TRIM CLIPS <i>re</i>	10.00	0.00	*27.00 FL
12	1		*REAR BUMPER TOP <i>de</i>	10.00	0.00	*690.00 FL
13	1		*REAR BUMPER LOWER <i>de</i>	10.00	0.00	*292.00 FL
14	2		*REAR BUMPER REFLECTOR <i>LH X / RH - ?</i>	10.00	0.00	*88.00 FL
15	2		*REAR BUMPER SENSOR <i>re</i>	10.00	0.00	*518.00 FL
16	1		*REAR BUMPER SENSOR WIRE <i>?</i>	10.00	0.00	*265.00 FL
17	1		*REAR BUMPER REINFORCEMENT <i>?</i>	10.00	0.00	*296.00 FL
18	2		*REAR BUMPER BRACKET L+R <i>?</i>	10.00	0.00	*136.00 FL
19	10		*REAR BUMPER CLIPS <i>re</i>	10.00	0.00	*48.00 FL
20	1		*REAR KEYLESS SENSOR <i>?</i>	10.00	0.00	*195.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,917.00
- List Item Discount on L Items (S\$)	491.70
Total Parts (S\$)	4,425.30

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

2021

Estimate Report

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CUT & WELD REAR PANEL, REAR LAMP PANEL. TO REPAIR REAR FENDER L+R, REAR FLOOR PANEL, TO REMOVE & REFIX DAMAGED PART, STRAIGHTEN & REALIGN AFFECTED AREAS	New	600	700.00
2	TO SPRAY AFFECTED AREAS	New	650	750.00
3	TO REMOVE & REFIX REAR LAGGAGE COMPARTMENT SIDE COVER, SIDE GARNISH, SIDE TRIM BOARD CARPET & OTHER ATTACHMENT PARTS	New	40	60.00
4	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	30	50.00
5	TO RUST PROOF AFFECTED AREAS	New	90	60.00

Gross Labour Cost (\$\$)

1,620.00

Report was unsubmitted during this print-out.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
the 900 100 68
6 days
48
03/03/21 @ 1050
Resue after repair