

ESTIMATE*

NO SH6955M
HYUNDAI
I-40

DATE 12/02/21 12:00 AM
MVA CHIANG/NTUC

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|-------------------------------|------|---------------------|-------------------|
| 1 | REAR DOOR PANEL LH | | | \$2,201.10 |
| 1 | REAR BUMPER | | | \$1,106.00 |
| 1 | REAR BUMPER SIDE BRACKET LH | | | \$35.60 |
| 1 | REAR WHEEL CAP LH | | 1323.20 | \$217.20 |
| | SUB TOTAL | | | \$3,559.90 |
| | 20.00% | 20% | 1058.56 | \$711.98 |
| | DISCOUNTED TOTAL | | | \$2,847.92 |
| 1 | REAR DOOR COMFORT APP STICKER | | 80 | \$80.00 |
| | | | | \$80.00 |
| | Labour Charge | | | |
| | Panel Beating | | | \$750.00 |
| | Spray Painting Charge | | | \$800.00 |
| | Remove/refix door parts | | 1170 | \$180.00 |
| | Tuff coat | | | \$120.00 |
| | TOTAL LABOUR | | 2308.56 | \$1,850.00 |
| | ESTIMATE TOTAL | | 4194/1850 3 days | \$4,777.92 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | | |

Tanjin 97495749
WP' 11/2/20 04pm
L/S Resurvey after repair
Tanjin e/Mantoon
2-3 days
4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis