

REPAIR ESTIMATE*

VEHICLE NO SHB6337J

MAKE :

14/02/21

MODEL IONIQ G

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET RH /LH		\$111.60
10	REAR BUMPER CLIPS		\$22.00
1	REAR BUMPER REINFORCEMENT		\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH		\$276.20
1	BOOTLID		\$2,480.40
1	BOOTLID LOCK UPPER		\$224.00
1	BOOTLID H EMBLEM		\$28.00
1	BOOTLID HYBRID		\$24.30
1	BOOTLID LONIQ		\$31.30
2	BOOTLID LAMP LH /RH		\$1,588.80
1	BOOTLID UPPER GLASS		\$907.20
1	BOOTLID LOWER GLASS		\$584.90
2	TAIL LAMP LH/RH		\$1,740.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER LOWER MOULDING		\$155.00
1	REAR BUMPER FOG LAMP		\$201.50
2	NUMBER PLATE LAMP LH/RH		\$170.60
1	REAR BUMPER CENTRE UNDER COVER		\$123.85
1	REAR END PANEL		\$532.00
1	REAR PANEL GARNISH		\$346.80
2	REAR BUMPER REFLECTOR LH /RH		\$82.90
1	ANTENNA ASSY -SMART		\$40.50
1	REAR BUMPER TOW COVER		\$98.80
SUB TOTAL			\$11,076.90
20.00%			\$2,215.38
DISCOUNTED TOTAL			\$8,861.52
1	REAR NUMBER PLATE/W HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
1	BOOTLID APP LOGO STCKER		\$40.00
2	BOOTLID COMFORT LOGO/TEL NO. STICKER		\$60.00
10.00%			\$301.50
Labour Charge			
Panel Beating			\$1,400.00
Spray Painting Charge			\$800.00
Check wiring			\$60.00
Diagnose/reset erase fault code			\$240.00
Tuff Kote			\$120.00
Remove/refix Reverse sensor			\$60.00
TOTAL LABOUR			\$2,680.00
ESTIMATE TOTAL			\$11,843.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

7064.10

5651.28

\$41.45

335
10/30/50

Tamplin 9749 5749
WP 16/2/21 @ 4pm
P/P Resurvey before paint.
tamplin/klank-wan 26/0
4-5 days

\$7,962.78

LS \$6350

5 days