



Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

21 October 2021

Our Reference : SLH7860D

Your Reference : SHD2456P

India International Insurance Pte Ltd

64 Cecil Street

#04-02

Singapore 049711

Attn: Motor Claims Dept.

Dear Sir,

Subject: Accident Involving SLH7860D and SHD2456P along Yishun Ave 1 on 14/02/2021

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. SHD2456P.

We quantify our client's claim as follows:

1.	Cost of Repair	S\$	2,461.00
2.	Loss of Use (\$100 X 4 days)	S\$	400.00
3.	TP Insurer Search Fees	S\$	-
	Total	S\$	2,861.00

We hereby append the following relevant documents for your perusal:

- I. Repair bill tax invoice
- II. Letter of authority

Please let us know within the next 14 days from the received of this letter, whether you are prepared to accept all the above amount.



Best regards,


Yin Siew

Customer Service Advisor, Motor Claims

Goldbell Engineering Pte Ltd

Mobile : 9763 6433

Email : konyinsiew@goldbell.com.sg





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 1

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-02 IOB BUILDING
SINGAPORE 049711

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : EXI00296476
Invoice Date. : 21-10-2021
Account No. : C00001902
Quotation No. : 127901
Work Order No. : 1174898
Service Centre. : ANG MO KIO
Agreement No. : GBE~61814


PARTICULARS		AMOUNT SGD		
Reg No	: SLH7860D			
Chassis No	: ZSU600015944			
Engine No	: 3ZRB389681			
Model No	: TOYOTA HARRIER			
Mileage	: 0			
SRR No	:			
ACCIDENT REPAIR: GBE/SVC/SALES-AMK95				
DATE OF ACCIDENT: 14/02/2021				
POLICY NO.: AVPPSB0551422002				
**** TP CLAIM - INDIA ****				
	<u>Description</u>	<u>QTY</u>	<u>Disc</u>	<u>Net Price</u>
	COSTS OF REPAIR - LUMP	1	N	2300.00
	SUM			2300.00
			Parts Charges:	2300.00
			Sub Total:	2300.00
			GST @ 7.00 %	161.00
	E. & O. E			
			TOTAL	2461.00

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD.
When making payment, please quote our invoice numbers.
No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.



LETTER OF AUTHORITY

I/We, Ngo Yun Ling Joanne, owner of SLH7860D (Vehicle no.) hereby authorize GOLDBELL ENGINEERING PTE LTD to act on my/our behalf with respect to my/our claim for repair costs and/or rental and/or loss of use for my vehicle no. SLH7860D that was damage pursuant to the accident which occurred on 14/02/2021 at/along Yishun Ave 1 involving vehicle no. SHD2459P.

I/We permit GOLDBELL ENGINEERING PTE LTD to have full discretion to settle my/our above-mentioned claim in a manner that they deem fit and to sign any discharge voucher or receive any payment on my/our behalf further to the settlement of my/our claim with payment cheque/s being made in favor of GOLDBELL ENGINEERING PTE LTD.


I/We authorize GOLDBELL ENGINEERING PTE LTD to have full discretion in the usage of my/our (owner and or driver) NRIC, work permit, driving license and whatsoever identification card, indemnity against PDPA terms and conditions.

I/We acknowledge that any settlement that GOLDBELL ENGINEERING PTE LTD may reach on my/our behalf is in full and final settlement of my/our property damage claims against the owner/ driver/ motor insurer of the third party vehicle bearing registration number SHD2456P and is on a without prejudice / without admission of liability basis insofar as the driver/ owner/ motor insurer of vehicle concerned.

Date this 15 day of 2 (month) 2021 (year)

ClaimantVehicle Driver


(Vehicle owner or Company representative)




Signature




Signature




Full name as per Identity card



Full name as per Identity card



Company Stamp if applicable



Company Stamp if applicable

Kon Yin Siew

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Wednesday, October 20, 2021 5:02 PM
To: Kon Yin Siew
Subject: RE: Finalize - SLH7860D - DOA : 14/02/2021

L/Sump \$2300.00, 4days confirmed.

From: Kon Yin Siew <KonYinSiew@goldbell.com.sg>
Sent: Wednesday, 20 October 2021 4:29 pm
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: William Oh Soon Lee <WilliamOhSL@goldbell.com.sg>; Ramesh <Ramesh@goldbell.com.sg>
Subject: Finalize - SLH7860D - DOA : 14/02/2021

Hi Kenneth,

Please refer to the after paint photo.

Can we finalise the cost of repair @ L/S \$2,300.00?

Thank you.

NOTICE:

In response to the escalating Covid-19 cases, please refrain from sending hardcopy documents to us as delays are to be expected for handling hardcopy documents.

All correspondence should be made via email instead. Any inconvenience caused is much regretted.

Kon Yin Siew | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6861 0007 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 9739 6433 |