



Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

Page 1 / 2

ESTIMATE

Date : 16/02/2021
 To : INDIA INTERNATIONAL INSURANCE PTE LTD
 Attn. : *Not Attached*
 Office / Mobile : *61 Rm 8*
 Email Address : *Meany Alex Paim*
 From : GOLDBELL ENGINEERING PTE LTD
 Attn. : KONYINSIEW *4 days*
 Office / Mobile : +65 6861 0007
 Email / Fax No. : KonYinSiew@goldbell.com.sg
 Reg No : SLH7860D
 Model : TOYOTA HARRIER
 Chassis No : ZSU600015944
 Engine No : 3ZRB389681
 Quotation No. : 127901
 Ref. No. :
 D.O.A. : 14/02/2021
 Policy No. :
 Claim Type : TP CLAIMS - INDIA
 Workshop : ANG MO KIO

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		HEADLAMP LH	1	2,150.00	-25	1,612.50	1,612.50 ✓
2		FRONT FENDER LH	<i>Bu</i> 1	980.00	-25	735.00	735.00 ✓
3		FRONT BUMPER	<i>Bu</i> 1	755.00	-25	566.25	566.25 ✓
4		FRONT BUMPER RETAINER LH	<i>Di</i> 1	35.00	-25	26.25	26.25 ✓
5		FRONT BUMPER TOW COVER	1	65.00	-25	48.75	<i>in</i> 48.75 ✓
6		FRONT BUMPER LOWER GRILLE	1	312.00	-25	234.00	<i>in</i> 234.00 ✓
7		FRONT FOG LAMP COVER LH	<i>in</i> 1	128.00	-25	96.00	96.00 ✓
8		FRONT FOG LAMP	<i>in</i> 1	198.00	-25	148.50	148.50 ✓
9		HEADLAMP SUPPORT PANEL LH	<i>n</i> 1	280.00	-25	210.00	210.00 ✓
PARTS TOTAL :							3,677.25

SPECIAL NETT ITEMS

1	FRONT BUMPER CLIPS (SET)	1	<i>na</i> 30.00 ✓
PARTS TOTAL:			30.00

LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS		1800.00
2	TO REPAIR AND ALIGN LH FRONT DOOR	<i>na</i> 300.00 ✓	
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	<i>200</i> 100.00	
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	<i>For</i> 1400.00	

LABOUR TOTAL :	3,600.00
SUB-TOTAL :	7,307.25
GST @ 7% for \$ 7,307.25	511.51
GRAND TOTAL (S\$) :	7,818.76

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: