**MESSAGES** 

**CLAIMS** 



General & Workshop Deta	ils Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labou	ır Miscellaneous	Summary			
General Details			Workshop Details						
Involving	TPVD Nissan (SLA4145S)		Total Rebate Am	nount 29	29553				
Date of Loss	9 February 2021		Nett Loss Amou	nt -\$29	-\$29,553.00				
Time of Loss	18.25		Assigned Works	hop LKK	LKK AUTO CONSULTANTS PTE LTD (TP)				
Loss Description	SLN3396Y (INSD) > SLA4145S > 5	SMX3269S	Days of work completion *	20	20				
Comment			Completion						

**MESSAGES** 

**CLAIMS** 



General & Worksho	p Details .	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & La	abour M	liscellaneous	Summar	У
Vehicle & Driver D	etails								
Vehicle Registration#	SLA414	15S		Purchase Date		dd/mm/yyy	/Y		
Registration State	SING	APORE		Registration Date * 29/02/201			2016		
Mileage	60323	3		Age of Vehicle		4			
CATEGORY	POLICY INFORMATIC	ASSESSMENT INFO	ORMATION	Driver Details					
Manufacturing		2016		CATEGORY	FNO INFO	DRMATION		SURVEY	
Year				Driver Name		NATHAN YEE NXIAN			
Make	TPVD	NISSAN		Data of Dirth			11/		<del></del>
				Date of Birth			dd/	mm/yyyy	

Model CATEGORY	POLICY INFORMATION	NOTE 1.2 CVT ABS D/A	<b>CATEGORY</b> Age	FNOL INFORMATION	POST SURVEY INFORMATION
Туре		•	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		JN1TAAE12Z0972186	Driving Experience	0	
Engine No		HR12167510B	Driver License #		
Engine Capacity		1198	License Type		•
Sum Insured		0	License Issue Date		dd/mm/yyyy ##
Market Value		0	License Expiration Date		dd/mm/yyyy 🏥

FNOL	POST SURVEY
INFORMATION	INFORMATION
Singapore	
Personal Correspondence	
Unknown	
Unknown	•
TBC	
	Personal Correspondence Unknown

**MESSAGES** 

**CLAIMS** 



General & Workshop Deta	ils Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labo	our	Miscellaneous	Summary		
Detailed Assessment			Condition of Vehicle at time of survey						
Inspection Date *	18/02/2021		General conditio	on I	Fair			~	
Total Loss	Yes No		Steering (Service	eable)	Yes	No			
Towing Charges	0		Footbrake (Servi	ceable)	Yes	No			
Voluntary Excess  Compulsory Excess	0		Handbrake (Serviceable)		Yes	No			
Young/Inexperienced/ Unnamed Driver Excess	0		Engine Modifica	tion	Yes	No			
LACESS			Pre-accident cor	ndition	Fair			~	

Other Excess		Tyre Condition	
Age of Tyres		Spare wheel	
Front Tyre Size	185/65R15	Rear Tyre Size	185/65R15
Front left side	CONTINENTAL6mm	Rear left side	CONTINENTAL6mm
Front right side	CONTINENTAL6mm	Rear right side	CONTINENTAL6mm

**MESSAGES** 

**CLAIMS** 



General & Workshop Details	Vehicle & Driver Details	Vehicle Conditi	on Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Tax Eligibility & Additiona	al Deduction for Parts					
Depr./Bttr%			Salvage%			
Discount%	10		Settlement%	100		
Paint Labour/Material Ra	tio					
Paint Labour Ratio	20		Paint Material R	atio 80		
Cash Loss		<b>Y</b> es N	o			
Part Supplied by AXA		Yes N	o			

MESSAGES

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio

CLAIMS



Parts	Априлага													
	A													
Add	Approve	Deny	Submit All											
-	EDIT	SR NO	QUAN MATERIAL TITY	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1	FRONT BUMPER	Deformed	0	394.3	No		10			354.87	Reviewinį
	Ď	0	2	FRONT BUMPER RETAINER	Bent	0	26	No		10			46.8	Reviewinį
	Ø	0	1	FRONT BUMPER SPONGE	Damaged	0	168	No		10			151.2	Reviewinį
	Ď	0	1	FRONT BUMPER REINFORCEMENT	Repair	0	0	No		10			0	Deny
	Ď	0	1	FRONT HEADLAMP LH	Cracked	0	658	No		10			592.2	Reviewinį
	Ď	0	1	FRONT HEADLAMP RH	Serviceable	0	0	No		10			0	Deny
	Ø	0	2	FRONT HEADLAMP BRACKET	Serviceable	0	0	No		10			0	Deny
	Ď	0	1	FRONT BUMPER TOP COVER	Deformed	0	194	No		10			174.6	Reviewinį

Parts & Labour Miscellaneous

Summary

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
Ď	0	1		FRONT GRILLE ASSY	Cracked	0	276.7	No		10			249.03	Reviewinį
P	0	1		FRONT GRILLE EMBLEM	Necessary	0	59	No		10			53.1	Reviewinį
Ď	0	1		FRONT FOG LAMP LH	Serviceable	0	0	No		10			0	Deny
ø	0	1		FRONT FOG LAMP RH	Serviceable	0	0	No		10			0	Deny
Ø	0	1		REAR BUMPER	Deformed	0	607	No		10			546.3	Reviewinį
Ø	0	2		REAR BUMPER RETAINER	Bent	0	32	No		10			57.6	Reviewinį
Ď	0	2		REAR BUMPER BRACKET	Serviceable	0	0	No		10			0	Deny
Ď	0	1		REAR BUMPER DAMPER O/S	Dented	0	91.7	No		10			82.53	Reviewinį
Ø.	0	1		REAR BUMPER DAMPER N/S	Serviceable	0	0	No		10			0	Deny
Ø	0	1		TAILGATE	Dented	0	998	No		10			898.2	Reviewinį
P	0	1		TAILGATE HINGE LH	Serviceable	0	0	No		10			0	Deny
P	0	1		TAILGATE HINGE RH	Serviceable	0	0	No		10			0	Deny
P	0	1		TAILGATE DAMPER LH	Serviceable	0	0	No		10			0	Deny

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
Ď	0	1		TAILGATE DAMPER RH	Serviceable	0	0	No		10			0	Deny
Ø	0	1		TAILGATE LOCK	Dented	0	156	No		10			140.4	Reviewinį
Ď	0	1		TAILGATE SHOCK STRIKER	Serviceable	0	0	No		10			0	Deny
Ø	0	1		TAILGATE INNER TRIM	Deformed	0	156	No		10			140.4	Reviewinį
P	0	1		TAILGATE OUTER GARNISH	Cracked	0	211.9	No		10			190.71	Reviewinį
P	0	1		TAILGATE EMBLEM LOGO	Necessary	0	45	No		10			40.5	Reviewinį
Ď	0	1		TAILGATE EMBLEM - NOTE	Necessary	0	62.7	No		10			56.43	Reviewinį
Ď	0	1		REAR WINDSCREEN MOULDING	Necessary	0	67	No		10			60.3	Reviewinį
Ø	0	1		KEYLESS SENSOR	Serviceable	0	0	No		10			0	Deny
Ø	0	1		END PANEL	Dented	0	477.8	No		10			430.02	Reviewinį
Ø	0	1		END PANEL TOP GARNISH	Twisted	0	83	No		10			74.7	Reviewinį
Ď	0	1		FLOOR PANEL	Repair	0	0	No		10			0	Deny
Ď	0	1		SPARE TYRE TOP BOARD	Damaged	0	411	No		10			369.9	Reviewinį

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	Ď	0	1		FENDER INNER TRIM LH	Deformed	0	398	No		10			358.2	Reviewinį
	Ď	0	1		FENDER INNER TRIM RH	Deformed	0	398	No		10			358.2	Reviewinį
	P	0	1		TAILGATE WIPER MOTOR	Serviceable	e 0	0	No		10			0	Deny
	P	0	1		TAILGATE WIPER BLADE	Serviceable	e 0	0	No		10			0	Deny
	Ø	0	1		REAR TAILLAMP LH	Cracked	0	381	No		10			342.9	Reviewinį
	Ø	0	1		REAR TAILLAMP RH	Cracked	0	381	No		10			342.9	Reviewinį
	Ø	0	1		REAR EXHAUST ASSY	Serviceable	e 0	0	No		10			0	Deny
	Ø	0	1		REAR EXHAUST MOUNTING	Serviceable	e 0	0	No		10			0	Deny
Labour															
Add	Approve	Deny	Submit /	All											
	EDIT	SR NO	REPA (LAB	IR/REPLACE OUR)	PART NAME		ESTIMATE LABOUR AMOUNT	ADJUSTED I AMOUNT		ESTIMATE PAINT AMOUNT		DJUSTED PAINT MOUNT		FION BOUR)	COMMENT
	Ø	0			CHECK ALL WIRI		0	30		0	0		Rev	viewing	
	Ø	0			REMOVE AND RE		0	50		0	0		Rev	viewing	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
Ø.	0		REMOVE, REFIT REAR LINING, TRIM AND GARNISH	0	80	0	0	Reviewing	
Ø	0		REMOVE AND RENEW REAR EXHAUST	0	0	0	0	Deny	
Ø	0		REMOVE AND REFIT REAR WINDSCREEN	0	120	0	0	Reviewing	
Ø	0		REMOVE AND REFIT FUEL TANK	0	0	0	0	Deny	
Ď	0		TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	0	60	0	0	Reviewing	
Ø	0		PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	0	1000	0	0	Reviewing	
Ø	0		SPRAY PAINTING ON AFFECTED AREAS	0	1580	0	0	Reviewing	
Ø	0		APPLY ANTI RUST ON AFFECTED AREAS	0	0	0	0	Deny	

**MESSAGES** 

CLAIMS



Genera	al & Worksho	p Details	Vehicle & Driver Details Vehicle Condition			Taxes & Ratio	Parts & Labour	Miscellaneous •	Summary
Add	Approve	Deny	Submit All						
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE	
		0	DAYS OF REPAIR : 8 DAYS	Reviewing		0		ŵ	
	Ø	0	FRONT NUMBER PLATE	Reviewing		40	BENT	ш	
	Ø	0	SET FRONT BUMPER CLIP	Reviewing		30	NECESSARY	ш	
	D	0	SET FRONT GRILLE CLIP	Deny		0	NOT NECESSARY	ŵ	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
P	0	REAR NUMBER PLATE	Reviewing		40	BENT	ŵ
P	0	SET REAR BUMPER CLIP	Reviewing		30	NECESSARY	ŵ
Ø	0	SET REAR TAILGATE INNER TRIM CLIP	Reviewing		30	NECESSARY	ŵ
P	0	SET REAR REVERSE SENSOR	Reviewing		200	SHORTED	â
P	0	REAR REVERSE CAMERA	Reviewing		300	SHORTED	ŵ
Α	^	JOINT	D		50	NECECCA DV	a

 EDIT	SR NO	SEALAN I <b>MAME</b> PANEL	Keviewing ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	NECESSARY COMMENT	IIII REMOVE
P	0	REAR WINDSCREEN SEALANT	Reviewing		40	NECESSARY	<b>d</b>

**MESSAGES** 

**CLAIMS** 



## **Assessment Details**

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$9,791.9	99	
CATEGORY		ESTIMATE	ADJUSTED				
Spare Parts		\$0.00	\$6,111.99				
Labour		\$0.00	\$2,920.00				
Miscellaneous		\$0.00	\$760.00				

Submit for Review

**MESSAGES** 

**CLAIMS** 



General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Rat	tio Parts & L	abour	Miscellaneous	Summa
Add	Approve	Deny	Submit All							
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMO\	/E	
	<i>i</i>	0	FINAL LUMP SUM	Reviewing		7800		ů		

**MESSAGES** 

**CLAIMS** 



## **Assessment Details**

General & Workshop	Details .	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$7,800.0	00	
CATEGORY		ESTIMATE	ADJUSTED				
Miscellaneous		\$0.00	\$7,800.00				
						_	

Submit for Review