

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Lukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

GERALD ANG WEE KHENG

BLK 81 BEDOK NORTH RD #08-290

SINGAPORE 460081

Contact : 97977775

TPAXA
Xiao Tong.

ESTIMATE

Repair Code : CLM15185

Date in : 16/02/2021

Vehicle Num. : SGW386H

Model : TOYOTA C-HR 1.8G HYBRID A

Chassis/Eng# : ZYX102027084/2ZR8073544

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented.</i>	1	1347.10	✓ 1,347.10
FRONT LH DOOR CHECKER <i>Heam</i>	1	183.80	X 183.80
FRONT LH DOOR GLASS REGULATOR <i>Damaged</i>	1	248.20	✓ 248.20
FRONT LH DOOR GLASS REGULATOR MOTOR <i>not nec</i>	1	926.00	X 926.00
FRONT LH DOOR HINGE (LOWER) <i>3 nec</i>	1	97.50	X 97.50
FRONT LH DOOR HINGE (TOP)	1	97.50	X 97.50
FRONT LH DOOR INNER BLACK TAPE (LONG) <i>new</i>	1	21.90	✓ 21.90
FRONT LH DOOR INNER TRIM BOARD <i>curled.</i>	1	1248.00	✓ 1,248.00
FRONT LH DOOR MECHANISM LOCK <i>the nec</i>	1	561.90	X 561.90
FRONT LH DOOR OUTER BLACK TAPE (VERTICAL) <i>new</i>	1	43.50	✓ 43.50
FRONT LH DOOR OUTER FRAME RIVET <i>new</i>	8	5.00	✓ 40.00
FRONT LH DOOR OUTER GARNISH <i>the nec</i>	1	145.00	✓ 145.00
FRONT LH DOOR PROTECTOR <i>ut</i>	1	345.80	✓ 345.80
FRONT LH DOOR WEATHER STRIP <i>the nec</i>	1	180.10	X 180.10
FRONT LH FENDER <i>Reps</i>	1	845.00	X 845.00
FRONT LH FENDER 'HYBRID' EMBLEM <i>new</i>	1	59.80	✓ 59.80
FRONT LH FENDER ARCH GARNISH <i>ut</i>	1	147.50	✓ 147.50
FRONT LH FENDER INNER SHIELD <i>not nec</i>	1	243.70	X 243.70

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GERALD ANG WEE KHENG
BLK 81 BEDOK NORTH RD #08-290
SINGAPORE 460081

Contact : 97977775

ESTIMATE

Repair Code : CLM15185

Date in : 16/02/2021

Vehicle Num. : SGW386H

Model : TOYOTA C-HR 1.8G HYBRID A

Chassis/Eng# : ZYX102027084/2ZR8073544

FRONT LH KNUCKLE ARM	1	698.50	+	698.50
FRONT LH KNUCKLE ARM BEARING	1	697.10	+	697.10
FRONT LH LOWER ARM	1	760.10	+	760.10
FRONT LH SHOCK ABSORBER	1	493.60	+	493.60
FRONT LH SHOCK ABSORBER TOP MOUNTING	1	236.40	X	236.40
FRONT LH SPORT RIM	1	2128.20	+	2,128.20
FRONT LH TIE ROD END	1	186.70	+	186.70
REAR BUMPER	1	353.10	+	353.10
REAR BUMPER LH END SEAL COVER	1	109.00	+	109.00
REAR BUMPER LH REFLECTOR GARNISH	1	67.80	+	67.80
REAR BUMPER LOWER LID	1	372.70	+	372.70
REAR BUMPER SIDE RETAINER L/R	2	118.90	+	237.80
REAR LH CONTROL ARM	1	239.20	✓	239.20
REAR LH DOOR	1	1254.20	✓	1,254.20
REAR LH DOOR CHECKER	1	183.80	+	183.80
REAR LH DOOR GLASS REGULATOR	1	248.20	✓	248.20
REAR LH DOOR HINGE (LOWER)	1	97.50	X	97.50
REAR LH DOOR HINGE (TOP)	1	97.50	X	97.50

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

GERALD ANG WEE KHENG

BLK 81 BEDOK NORTH RD #08-290

SINGAPORE 460081

Contact : 97977775

ESTIMATE

Repair Code : CLM15185

Date in : 16/02/2021

Vehicle Num. : SGW386H

Model : TOYOTA C-HR 1.8G HYBRID A

Chassis/Eng# : ZYX102027084/2ZR8073544

REAR LH DOOR INNER BLACK TAPE (LONG)	1	21.90	✓	21.90
REAR LH DOOR INNER BLACK TAPE (VERTICAL)	1	43.50	✓	43.50
REAR LH DOOR INNER TRIM BOARD	1	686.80	✓	686.80
REAR LH DOOR OUTER FRAME RIVET	8	5.00	✓	40.00
REAR LH DOOR OUTER GARNISH	1	209.60	145 ✓	209.60
REAR LH DOOR PROTECTOR	1	209.60	✓	209.60
REAR LH DOOR WEATHER STRIP	1	152.70	✓	152.70
REAR LH FENDER	1	1031.30	X	1,031.30
REAR LH FENDER ARCH GARNISH	1	147.50	✓	147.50
REAR LH FENDER INNER SHIELD	1	243.70	X	243.70
REAR LH KNUCKLE ARM	1	822.30	655 ✓	822.30
REAR LH KNUCKLE ARM BEARING	1	801.50	344 ✓	801.50
REAR LH LOWER ARM	1	497.50	✓	497.50
REAR LH SHOCK ABSORBER	1	117.20	X	117.20
REAR LH SPORT RIM	1	2128.20	800 (SW) ✓	2,128.20
REAR LH UPPER ARM	1	420.80	✓	420.80
ROCKER GARNISH LH	1	563.80	✓	563.80

*** This is a computer-generated document which requires no signature.***

page 3

9316.30

6987.22

S.N. 800.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

GERALD ANG WEE KHENG

BLK 81 BEDOK NORTH RD #08-290

SINGAPORE 460081

Contact : 97977775

ESTIMATE

Repair Code : CLM15185

Date in : 16/02/2021

Vehicle Num. : SGW386H

Model : TOYOTA C-HR 1.8G HYBRID A

Chassis/Eng# : ZYX102027084/2ZR8073544

Subtotal before discount		23,381.60
Percentage discount 25%		5,845.40
Sub-total 1		17,536.20
FRONT LH 225/55ZR18 TYRE <i>NH NH</i>	1	380.00 <i>X</i> 380.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>NH</i>	1	50.00 <i>30</i> 50.00
FRONT LH DOOR OUTER WEATHER STRIP SEAL <i>NH NH</i>	1	50.00 <i>X 30</i> 50.00
FRONT LH DOOR PROTECTOR CLIPS - SET <i>NH</i>	1	50.00 <i>30</i> 50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>NH</i>	1	40.00 <i>20</i> 40.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>NH NH</i>	1	50.00 <i>X</i> 50.00
REAR BUMPER CLIPS - SET <i>NH NH</i>	1	50.00 <i>X</i> 50.00
REAR LH 235/50R18 TYRE <i>NH NH</i>	1	380.00 <i>X</i> 380.00
REAR LH DOOR INNER TRIM BOARD CLIPS - SET <i>NH</i>	1	50.00 <i>30</i> 50.00
REAR LH DOOR OUTER WEATHER STRIP SEAL <i>NH NH</i>	1	50.00 <i>X</i> 50.00
REAR LH DOOR PROTECTOR CLIPS - SET <i>NH</i>	1	50.00 <i>30</i> 50.00
REAR LH FENDER ARCH GARNISH CLIPS - SET <i>NH</i>	1	40.00 <i>20</i> 40.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>NH NH</i>	1	50.00 <i>X</i> 50.00
ROCKER GARNISH LH CLIPS - SET <i>NH NH</i>	1	50.00 <i>X</i> 50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GERALD ANG WEE KHENG
BLK 81 BEDOK NORTH RD #08-290
SINGAPORE 460081

Contact : 97977775

ESTIMATE

Repair Code : CLM15185
Date in : 16/02/2021
Vehicle Num. : SGW386H
Model : TOYOTA C-HR 1.8G HYBRID A
Chassis/Eng# : ZYX102027084/2ZR8073544

Subtotal before discount	1,340.00
Percentage discount 0%	0.00
Sub-total 2	1,340.00
Parts-total	18,876.20

LABOUR

To reset system after repair works

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	4,300.00
Parts & Labour Total	23,176.20

x 300.00
x 220 x 350.00
220 x 350.00
80 x 100.00
x 100.00
160 x 180.00
700 x 1,600.00
600 x 1,200.00
40. 120.00

1800.

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 9747.22
H/S: 7.81C.

06 Days.

7.8