



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:VALE OH

Ref: CC4/ASM21002276/Ars3q2
Date: 18/01/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|----------|-----------------------|------------|
| Insured Veh. | SHD 730K | Veh. Inspected | SKZ 6247Z |
| Policy No. | P2413997 | Coverage (\$) | 0.00 |
| Claim No. | S1M032YZ | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 17/02/2021 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|----------------|---------------------|------------|
| Make & Model | TOYOTA HARRIER | c.c | 1986 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | ZSU600060432 | Colour | BLACK |
| Odometer | 183024 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|------------|-------------|---------|
| R/H Front Tyre | 235/55 R18 | BRIDGESTONE | 6 mm |
| L/H Front Tyre | 235/55 R18 | BRIDGESTONE | 6 mm |
| R/H Rear Tyre | 235/55 R18 | BRIDGESTONE | 6 mm |
| L/H Rear Tyre | 235/55 R18 | BRIDGESTONE | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 10/02/2021 | Inspection Date | 17/02/2021 |
| Survey held at | CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**