



CLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LAW YONG KHIANG (LIU YONGQIANG)	Cust No/Name	KCV09208/LAW YONG KHIANG (LIU YONGQIANG)
BLK 430B FERNVALE LINK	Reg No/Reg Date	SMD8668X / 05/09/201
#03-219	Date In/Mileage	/ 0
SINGAPORE 792430	Chassis No	GF7W0402021
Contact No	Engine No	4J11YP6169
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (9
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV09208	CRDVCH	17/02/2021/ 17:02		442 / CocoLu	62990
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000					1800 2250.00
RENEW FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT PANEL					
REPAIR FRT DOOR RH & LH @400 450					
E PNT88000					?Xnn 100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR					
A 54900099					?Xnn 80.00
TOP UP AIRCON GAS					
A 54900099					30.00
CHECK WIRING & ELECTRICAL SYSTEM					
A 10028901					120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					
E PNT88000					100.00
REMOVE & INSTALL FRT AIRDAM					
E PNT98000					2100 3150.00
SPRAY PAINT FOR FRT AIRDAM, FRT BUMPER, BONNET, FRT SUPPORT PANEL					
FRT FENDER RH & LH, FRT DOOR RH & LH @350					
M SUNDRY					nn X 50.00
FRT NUMBER PLATE WITH FRAME X					
M SUNDRY					40.00
APPLY SEALANT FOR ACCIDENT PORTION					
M SUNDRY					20.00
Sundry					
M FACE,FR BUMPER de		1133.00 1.00	1128.00	00.00	872.40 1128.00
M BRACKET,FR BUMPER SIDE,LH ?Xsvl		1.00	18.00	00.00	18.00
M BRACKET,FR BUMPER SIDE,RH ?Xsvl		1.00	18.00	00.00	18.00
M GARNISH,FR BUMPER,LH ?Xsvl		1.00	75.00	00.00	75.00
M GARNISH,FR BUMPER,RH ?Xsvl		1.00	75.00	00.00	75.00
M EXTENSION,FR BUMPER ?Xsvl		1.00	426.00	00.00	426.00
M BRKT,FR BUMPER SIDE,LWR LH ?Xsvl		1.00	6.00	00.00	6.00
M BRKT,FR BUMPER SIDE,LWR RH ?Xsvl		1.00	6.00	00.00	6.00
M GARNISH,FR BUMPER SIDE ?Xsvl		1.00	48.00	00.00	48.00
M GARNISH,FR BUMPER SIDE ?Xsvl		1.00	48.00	00.00	48.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

AGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



4977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LAW YONG KHIANG (LIU YONGQIANG)	Cust No/Name KCV09208/LAW YONG KHIANG (LIU YONGQIANG)
BLK 430B FERVALE LINK	Reg No/Reg Date SMD8668X / 05/09/201
#03-219	Date In/Mileage / 0
SINGAPORE 792430	Chassis No GF7W0402021
Contact No	Engine No 4J11YP6169
	Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV09208	CRDVCH	17/02/2021/ 17:02		442 / CocoLu	62990
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M GARNISH,FR BUMPER SIDE <i>crn</i>		1.00	220.00	00.00	169.40 220.00
M GARNISH,FR BUMPER SIDE <i>crn</i>		1.00	220.00	00.00	169.40 220.00
M GARNISH,FR BUMPER SIDE <i>xsul</i>		1.00	112.00	00.00	112.00
M GARNISH,FR BUMPER SIDE <i>xsul</i>		1.00	112.00	00.00	112.00
M MOULDING,FR BUMPER,RH <i>xsul</i>		1.00	116.00	00.00	116.00
M MOULDING,FR BUMPER,LH <i>xsul</i>		1.00	116.00	00.00	116.00
M MOULDING,FR WHEEL ARCH,RH <i>ne</i>		1.00	160.00	00.00	123.70 160.00
M MOULDING,FR WHEEL ARCH,LH <i>ne</i>		1.00	160.00	00.00	123.70 160.00
M REINFORCEMENT,FR BUMPER <i>bt</i>		1.00	503.00	00.00	388.85 503.00
M REINFORCEMENT,FR BUMPER <i>bt</i>		1.00	135.00	00.00	103.75 134.00
M REINF,FR BUMPER SIDE,RH <i>xsul</i>		1.00	69.00	00.00	53.13 69.00
M REINFORCEMENT,FR BMRP SIDE <i>xsul</i>		1.00	22.00	00.00	22.00
M REINF,FR BUMPER SIDE,LH <i>bt</i>		1.00	60.00	00.00	46.20 60.00
M COVER,FR BUMPER <i>xsul</i>		1.00	25.00	00.00	25.00
M COVER,HEADLAMP SUPT PANEL <i>de</i>		1.00	50.00	00.00	38.50 50.00
M GRILLE ASSY,RADIATOR <i>scn</i>		1.00	572.00	00.00	440.44 569.00
M BRACKET,RADIATOR GRILLE,LH <i>de</i>		1.00	13.00	00.00	10.01 13.00
M BRACKET,RADIATOR GRILLE,RH <i>de</i>		1.00	17.00	00.00	13.00 17.00
M HOOD <i>buc</i>		1.00	980.00	00.00	754.60 975.00
M HINGE,HOOD,LH <i>xsul</i>		1.00	68.00	00.00	68.00
M HINGE,HOOD,RH <i>xsul</i>		1.00	68.00	00.00	68.00
M INSULATOR,HOOD <i>xsul</i>		1.00	133.00	00.00	133.00
M WEATHERSTRIP,HOOD <i>xsul</i>		1.00	40.00	00.00	30.80 40.00
M WEATHERSTRIP,HOOD <i>xsul</i>		1.00	41.00	00.00	41.00
M LATCH,HOOD <i>xsul</i>		1.00	76.00	00.00	76.00
M FENDER,FR LH <i>buc</i>		1.00	688.00	00.00	529.76 688.00
M FENDER,FR RH <i>buc</i>		1.00	688.00	00.00	529.76 688.00
M SHIELD,FR WHEELHOUSE,LH <i>xsul</i>		1.00	164.00	00.00	164.00
M SHIELD,FR WHEELHOUSE,RH <i>xsul</i>		1.00	164.00	00.00	164.00
M PANEL,HEADLAMP SUPPORT,UPR <i>bt</i>		1.00	183.00	00.00	140.91 182.00
M PNL,HEADLAMP SUPT,UPR RH <i>xsul</i>		1.00	58.00	00.00	58.00
M PNL,HEADLAMP SUPT,UPR LH <i>xsul</i>		1.00	58.00	00.00	58.00
M HEADLAMP ASSY,LH <i>crn</i>		1.00	2125.00	00.00	1643.95 2125.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LAW YONG KHIANG (LIU YONGQIANG)	Cust No/Name	KCV09208/LAW YONG KHIANG (LIU YONGQIANG)
BLK 430B FERNVALE LINK	Reg No/Reg Date	SMD8668X / 05/09/201
#03-219	Date In/Mileage	/ 0
SINGAPORE 792430	Chassis No	GF7W0402021
Contact No	Engine No	4J11YP6169
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (9
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV09208	CRDVCH	17/02/2021/ 17:02		442 / CocoLu	62990			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	HEADLAMP ASSY, RH	✓		2135.00	1.00	2125.00	00.00	2125.00
M	LAMP ASSY, FOG, FR LH	✓			1.00	348.00	00.00	348.00
M	LAMP ASSY, FOG, FR RH	✓			1.00	348.00	00.00	348.00
M	HARNESS, FOG LAMP	✓			1.00	130.00	00.00	130.00
M	CONDENSER ASSY, A/C REFRIGE	✓			1.00	857.00	00.00	857.00
M	HOSE, A/C COMPR DISCHARGE	✓			1.00	191.00	00.00	191.00
M	PIPE, A/C CONDENSER OUTLET	✓			1.00	262.00	00.00	262.00
M	HOSE, A/C COMPR SUCTION	✓			1.00	235.00	00.00	235.00

Estimate

SURVEYOR NAME: PASUL - H/ 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 18/02/2021 @ 1530

REMARKS: 7 days + 2 = 9 days

EXCESS: TBA / REVERT

Pay before print

Confirm & accepted by

Nett	20,490.00
7% GST on	1434.30
Total Payable	21,924.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.