



AIG - OD CLAIM
SURVEY: 18/02/21
LKK - PASUL

VEHICLE NO : SMD 8668 X

MODEL : MIT/OUTLANDER 2.0 2WD CVT

WIP : 62990

Material	:	\$	<u>8,114.26</u>
Labour	:	\$	<u>5,010.00</u>
Sub-Total	:	\$	<u>13,124.26</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>12,524.26</u>
GST 7%	:	\$	<u>876.70</u>
Grand Total	:	\$	<u>13,400.96</u>
Finalise By/Date : <u>Larry on 03/03/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 09 WORKING DAYS + 4 days (2 wk. ends)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09208/LAW YONG KHIANG (LIU YONGQIANG) Reg No/Reg Date SMD8668X / 05/09/2018 Date In/Mileage 18/02/2021/ 28937 Chassis/Package GF7W0402021 /CS3P Engine No 4J11YP6169 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (992) Colour/Trim W01 WHITE PEARL / BK BLACK
18/02/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	03/03/2021/ 10:05	BLC	884 / Lauro Songcuan	62990		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1800.00
RENEW FRONT BUMPER, BONNET, FRONT FENDER RH & LH, REPAIR FRONT DOOR RH & LH							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
E PNT88000							100.00
REMOVE & INSTALL FRONT AIRDAM							
E PNT98000							2100.00
SPRAY PAINT FOR FRONT AIRDAM, FRONT BUMPER, BONNET, FRONT FENDER RH & LH, FRONT DOOR RH & LH							
M SUNDRY							40.00
APPLY SEALANT FOR AFFECTED PORTIONS							
M SUNDRY							20.00
SUNDRIES							
E PNT88000							450.00
RENEW FRONT SUPPORT CENTRE, REPAIR FRONT SUPPORT RH & LH							
E PNT98000							350.00
SPRAY PAINT FRONT SUPPORT PANEL RH & LH							
X EXC							-600.00
EXCESS FOR OWN DAMAGE CLAIM							
X FACE,FR BUMPER ✓				1128.00	1.00	*	1133.00 23.00 872.41
X GARNISH,FR BUMPER SIDE ✓					1.00		220.00 23.00 169.40
X GARNISH,FR BUMPER SIDE ✓					1.00		220.00 23.00 169.40
X MOULDING,FR WHEEL ARCH,RH ?					1.00		160.00 23.00 123.20
X MOULDING,FR WHEEL ARCH,LH ?					1.00		160.00 23.00 123.20
X REINFORCEMENT,FR BUMPER ?				503.00	1.00	*	505.00 23.00 388.85
X REINF,FR BUMPER SIDE,RH ?					1.00		69.00 23.00 53.13
X REINF,FR BUMPER SIDE,LH ?					1.00		60.00 23.00 46.20
X COVER,HEADLAMP SUPT PANEL ?					1.00		50.00 23.00 38.50
X GRILLE ASSY,RADIATOR ✓				569.00	1.00	*	572.00 23.00 440.44

* - change price

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/02/2021	Cust No/Name KCV09208/LAW YONG KHIANG (LIU YONGQIANG) Reg No/Reg Date SMD8668X / 05/09/2018 Date In/Mileage 18/02/2021/ 28937 Chassis/Package GF7W0402021 /CS3P Engine No 4J11YP6169 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (992) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	03/03/2021/ 10:05	BLC	884 / Lauro Songcuan	62990

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BRACKET,RADIATOR GRILLE,RH ?	1.00	17.00	23.00	13.09
X HOOD ✓	1.00	980.00	23.00	754.60
X WEATHERSTRIP,HOOD ✓	1.00	40.00	23.00	30.80
X FENDER,FR LH ✓	1.00	688.00	23.00	529.76
X FENDER,FR RH ✓	1.00	688.00	23.00	529.76
X PANEL,HEADLAMP SUPPORT,UPR ?	1.00	183.00	23.00	140.91
X HEADLAMP ASSY,LH ✓	1.00	2135.00	23.00	1643.95
X HEADLAMP ASSY,RH ✓	1.00	2135.00	23.00	1643.95
X COVER,FR BUMPER ✓	1.00	295.00	23.00	227.15
X BRACKET,RADIATOR GRILLE,LH ?	1.00	13.00	23.00	10.01
X CLIP,ENG ROOM COVER ✓	10.00	2.00	23.00	15.40
X RIVET,FR BUMPER ✓	6.00	5.00	23.00	23.10
X CLIP,RR BUMPER ✓	10.00	3.00	23.00	23.10
X REINFORCEMENT,FR BUMPER ?	1.00	135.00	23.00	103.95

2 TEXT
OD CLAIM - AIG
DOA: 16/02/2021
SURVEY: RASUL (LKK)
09 DAYS

* - change price

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	8,114.26	Nett	12,524.26
Labour	4,950.00	7% GST on	876.70
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00		
Sundry/Others	-540.00	Total Payable	13,400.96
Total(w/o GST)	12,524.26		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMD 8668 X

<u>Materials</u>		<u>Cost \$</u>
1	Cover, FR Bumper	295.00
2	Clip, Eng Room Cover (10 pcs)	20.00
3	Rivet, FR Bumper (6 pcs)	30.00
4	Clip, RR Bumper (10 pcs)	30.00
		<u>375.00</u>
23% Discount		<u>86.25</u>
		<u>288.75</u>
<u>Labour</u>		
1	Renew Front Support Ctr, Repair Front Support Panel RH & LH	450.00
2	Spray Paint Front Support Panel RH & LH	350.00
		<u>800.00</u>
Labour & Materials		1,088.75
7% GST		76.21
Total		<u>1,164.96</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SIN D 8668XWIP: 62990

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Renew fit support centre, repair fit	? / SUPP			
2	Support RH & LH, \$450	? / SUPP			
3	spray paint fit support \$350	? / SUPP			
4	REINFORCEMENT. FR BUMPER 54	? / SUPP			64004576
5	REINFORCEMENT FR BUMPER SIDE, LH	? / SUPP			6400D581
6	REINFORCEMENT FR BUMPER SIDE, RH	? / SUPP			6400D582
7	REINFORCEMENT, FR BUMPER 64	? / SUPP			640614899
8	Moulding, FR WHEEL ARCH, RH 100	? / SUPP			7407A646
9	Moulding, FR WHEEL ARCH, LH 100	? / SUPP			7407A645
10	PANEL, HEADLAMP SUPPORT, UPR 64	? / SUPP			5356C555
11	COVER, HEADLAMP SUPPORT UPR PANEL	? / SUPP			7450A753
12	BRACKET, RADIATOR GRILLE, LH 100	? / SUPP			6400D922
13	BRACKET RADIATOR GRILLE, RH 100	? / SUPP			6400D586
14	COVER FR BUMPER 54	? / SUPP			6400J046
15	CLIP, ENG RO (X10) 100	? / SUPP			MU488006
16	CLIP RR BUM (X10) 100	? / SUPP			MR288150
17	RIVET, FR BU (X6) 100	? / SUPP			MU001657
18		? / SUPP			
19	Total repair Add 2 days (total 9 days)	? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	24/2/11	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: outlanderSURVEYOR: Rasul

Reg No: SMD8668X

Before using MUT-3 ver unit to check all the cond.
to To Carry out Diagnostic

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2017MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPi/GDI/DIESEL	GAS_0E640000		No DTCS		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS		
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCS		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCS		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS		
SRS-AIR BAG	ORC_81047302		No DTCS		
Air Conditioner	AC_80080011	U0184	AUDIO CAN timeout	Active	
ETACS	ETACS_83040801	U0184 B16A4 B16A2 U0231 B2353	AUDIO CAN timeout Turn signal(RH) bulb outage Turn signal(LH) bulb outage RLS LIN timeout Ignition power supply (low)	Active Active Active Stored Stored	
Meter	MTR_84084001	U0184	AUDIO CAN timeout	Active	
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active	
KOS/IMMO/Keyless	KOS_8A880020	U0184	AUDIO CAN timeout	Active	
OSS	OSS_9588000B	U0184	AUDIO CAN timeout	Active	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GFTW 2017MY

For M01 SPD 86682

After very short test not unit to free all the good

to To Care out Dimple

to Job Don

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	GAS_0E640000		No DTCs		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
AT/CVT/A-MT/TTC-SST	CVT_14080300		No DTCs		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCs		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
SRS-AIR BAG	ORC_81047302		No DTCs		
Air Conditioner	AC_80080011		No DTCs		
ETACS	ETACS_83040801		No DTCs		
Meter	MTR_84084001		No DTCs		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		No DTCs		
