

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Cecilia.

Estimate Quotation

Quotation No	Feb 004/2021
Date	16/2/2021
Vehicle No	SJY793U
Make / Model	Toyota Ractis

SCP1000054797

To: AXA Insurance Singapore Pte Ltd
Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper <i>Dishend</i>		\$ 780.00
2 pcs	rear bumper side retainer <i>new</i>	\$ 98.00	\$ 196.00
1 set	rear bumper reverse sensor <i>Damaged</i>		\$ 250.00
1 pc	rear end panel <i>Dishend</i>		\$ 685.00
1 pc	rear end panel top garnish <i>Dishend</i>		\$ 258.00
1 set	rear end panel top garnish clip <i>new</i>		\$ 30.00
2 pcs	tail lamp <i>R.H. cracked</i>	\$ 455.00	\$ 910.00
1 pc	rear compartment top board <i>Deformed</i>		\$ 285.00
1 pc	tailgate <i>Distorted</i>		\$ 1,852.00
1 pc	tailgate glass sealant <i>new</i>		\$ 185.00
1 pc	tailgate Ractis emblem <i>new</i>		\$ 86.00
1 pc	tailgate outer chrome handle <i>new</i>		\$ 275.00
1 set	reverse camera <i>Damaged</i>		\$ 450.00
1 pc	tailgate inner lock <i>Damaged</i>		\$ 485.00
1 pc	tailgate w/strip <i>new</i>		\$ 344.00
2 pcs	tailgate absorber <i>new</i>	\$ 386.00	\$ 772.00
1 pc	o/s rear fender <i>Buckled</i>		\$ 985.00
1 pc	o/s rear fender inner garnish <i>cracked</i>		\$ 915.00
1 pc	o/s rear fender inner garnish clip <i>new</i>		\$ 30.00
1 pc	exhaust silencer <i>new</i>		\$ 955.00
1 pc	o/s rear mudflap <i>Dishend</i>		\$ 135.00
1 pc	o/s rear sports rim <i>new</i>		\$ 850.00
1 pc	o/s rear tyre <i>Run down</i>		\$ 275.00
1 pc	o/s rear absorber <i>new</i>		\$ 325.00
1 pc	o/s rear fender glass sealant <i>new</i>		\$ 340.00
1 pc	o/s rear wheel bearing <i>new</i>		\$ 875.00
1 pc	rear no.plate <i>new</i>		\$ 60.00
1 pc	axle beam <i>But</i>		\$ 1,785.00
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,500.00
2	to putty and spray painting on affected area		\$ 1,400.00
3	anti rust		\$ 180.00
4	R&R wiring		\$ 50.00
5	R&R tailgate glass		\$ 150.00
6	R&R o/s rear fender glass		\$ 100.00
7	R&R cushion seat carpet		\$ 100.00
8	R& replace exhaust silencer		\$ 80.00
9	R& replace reverse sensor		\$ 80.00
10	R& replace reverse camera		\$ 80.00
11	wheel alignment		\$ 120.00
12	w/undercarriage		\$ 320.00
13	king dolly towing charge		\$ 154.80
	Subtotal:		\$ 19,387.80

Adrian G

BEST SOLUTION AUTOCARE PTE LTD

4/5 18/2/21

to 11 0mz

Authorised Signature



BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Feb 004/2021
Date	16/2/2021
Vehicle No	SJY793U
Make / Model	Toyota Ractis

To: AXA Insurance Singapore Pte Ltd
Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>behind</i>		\$ 835.00
1 set	front bumper clip <i>m</i>		\$ 30.00
1 pc	n/s front bumper retainer <i>xen</i>		\$ 98.00
1 pc	front grille <i>could</i>	2573	\$ 295.00
1 set	front grille clip <i>xen</i>		\$ 30.00
1 pc	front mid grille <i>could</i>	2004.75	\$ 235.00
1 set	front mid grille clip <i>xen</i>		\$ 30.00
1 pc	front lower grille <i>at</i>		\$ 235.00
1 set	front lower grille clip <i>m</i>		\$ 30.00
1 pc	front number plate <i>Best</i>		\$ 60.00
1 pc	front bumper reinforcement bar <i>in Borted</i>		\$ 575.00
	<i>Headlamp LH could</i>		<i>987</i>
			<i>721</i>
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair	530	\$ 500.00
2	to putty and spray painting on affected area		\$ 500.00
3	anti rust		\$ 100.00
4	wiring check		\$ 80.00
	Subtotal:		\$ 3,553.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin L
L/S 19/02/21
Supplementary: 746
Total: 15045.3
L/S: 12K
(Child Days)

(12K)
(11 Days)

STY793u Supplementary.

Tailgate Inner Trim Board. cracked

385 ✓

Tailgate Inner Trim Board Clips. Nec

30 ✓

Rear RH Fender Air Grille. Deformed

58. ✓

Rear Exhaust Gasket Nec

35 ✓

488

366

To repair and straighten rear RH chassis member ~~400.~~
300.

To transfer tailgate fittings. 380 ~~150.~~ 80.

Supplementary: 746