

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: NG QUN XIONG KELVIN
 477C UPPER SERANGOON VIEW
 #11-586
 SINGAPORE 533477

Estimate No: MC1901756
 Date: 17 Feb 2021
 Policy No: P10260574R01
 Veh Reg No: SGZ6010L
 Make/Model: TOYOTA COROLLA
 AXIO 1.5X M

ATTN:

Your Ref No: SGZ6010L
 Claim Type: Third Party
 Accident Date: 15/02/2021
 TP Veh Reg No: SGX1691P

Not Notified
11/2/21
Returning After Repair
5 days

Estimate Repair Cost to Vehicle No :SGZ6010L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT BONNET	1 PC	<i>Bu</i> 1,041.60	✓
2 FRONT BONNET HINGE LH & RH	2 PC	<i>R</i> 139.40	x
3 FRONT BONNET INSULATOR CLIPS	10 PC	<i>na</i> 41.00	x
4 HEADLAMP RH	1 PC	<i>cm</i> 676.30	✓
5 FRONT GRILLE W CHROME MOULDING	1 PC	<i>cm</i> 442.20	✓
6 FRONT GRILLE CLIPS	1 PC	<i>na</i> 4.20	✓
7 FRONT BUMPER	1 PC	<i>cm</i> 551.40	✓
8 FRONT BUMPER SIDE RETAINER LH & RH	2 PC	<i>cl/di</i> 126.80	✓
9 FRONT BUMPER CLIPS	15 PC	<i>na</i> 63.00	✓
10 FRONT BUMPER REINFORCEMENT	1 PC	336.20	?
11 FRONT FENDER RH	1 PC	<i>Bu</i> 388.50	✓
12 RADIATOR SUPPORT PANEL	1 PC	<i>R</i> 876.30	?
13 AIR CON CONDENSER	1 PC	<i>na</i> 1,801.70	x
14 RADIATOR	1 PC	1,916.33	?
		8,404.93	
	Less 25%	2,101.23	6,303.70
Special Nett			
15 RADIATOR COOLANT	1 PC	30.00	?
16 NUMBER PLATE	1 PC	<i>cm</i> 35.00	✓
		65.00	65.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>201</i>
18 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	100.00	?
19 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	<i>500</i>
20 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL, FRONT DOOR RH.	1 PC	900.00	<i>800</i>
		1,940.00	1,940.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : NG QUN XIONG KELVIN
477C UPPER SERANGOON VIEW
#11-586
SINGAPORE 533477

Estimate No: MC1901756
Date: 17 Feb 2021
Policy No: P10260574R01
Veh Reg No: SGZ6010L
Make/Model: TOYOTA COROLLA
AXIO 1.5X M

ATTN:

Your Ref No: SGZ6010L
Claim Type: Third Party
Accident Date: 15/02/2021
TP Veh Reg No: SGX1691P

Estimate Repair Cost to Vehicle No :SGZ6010L

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 8,308.70
		Add GST @ 7%	581.61
		Total Amount Payable	S\$ 8,890.31

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED NINETY AND CENTS THIRTY ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: