

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4 GATE 2
#03-21
SINGAPORE 415875

LINDA LIAO
STK AUTO (S) PTE LTD

Date : 17/02/2021
To : MSIG INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : YANG CHENG

Certificate Number : V8010335
GREAT EASTERN

Accident Date : 9/2/2021

Vehicle Number : SGC8211G

Make & Model : TOYOTA ALPARD
ESTIMATED REPAIR COST DETAILS

AGH 3000096/8

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	RH REAR FENDER <i>Repr</i>	\$ 1,521.10	+
1	RH REAR DOOR <i>new</i>	\$ 2,078.70	+
1	RH REAR CORNER PANEL GARNISH <i>Delnd</i>	\$ 1,500.00	+
1	REAR BUMPER <i>Delnd</i>	\$ 1,853.00	+
1	REAR BUMPER REFLECTOR RH <i>new</i>	\$ 215.60	+
1	REAR BUMPER RETAINER RH <i>new</i>	\$ 65.00	+
1	REAR BUMPER RETAINER LH <i>new</i>	\$ 65.00	+
1	TAILGATE EMBLEM <i>new</i>	\$ 125.00	+
	Sub Total	\$ 7,423.40	
	DISCOUNT 25% on Parts	\$ 1,855.85	
	Total	\$ 5,567.55	
Special Nett Item			
10	REAR BUMPER CLIPS <i>new</i>	\$ 50.00	30
10	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	\$ 50.00	+
10	RH REAR FENDER INNER SHIELD CLIPS <i>new</i>	\$ 50.00	+
1	REAR BUMPER REVERSE SENSOR <i>nn</i>	\$ 650.00	
		\$ 800.00	
LABOUR CHARGE			
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$ 1,000.00	300
1	TO SPRAY PAINT ON ACCIDENT AREAS	\$ 1,000.00	350
1	TO REMOVE AND REFIT RH REAR DOOR GLASS	\$ 150.00	+
1	TO CONDUCT WIRNG AND REMOVE AND REFIT REVERSE	\$ 100.00	50
1	TO CONDUCT WHEEL ALIGNMENT	\$ 150.00	+
1	TO RUST PROOFING ACCIDENT AREAS	\$ 150.00	+
	Sub Total	\$ 2,550.00	
	Grand Total	\$ 8,917.55	

L/S 18/02/21

032 days.

Total: 1974.25

L/S 1550 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: