



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2101894

INV Date 23/03/2021

Reference CS/EQI21002292/R1vf3q2

Code EQI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SMR 5408B  
Insured Veh. SMM 9992E  
Claim No. DM21HO00225-JG  
Policy No.  
Accident Date 07/02/2021  
Inspection Date 18/02/2021

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>300.00</b>
<b>GST (7%)</b>	<b>21.00</b>
<b>Grand Total</b>	<b>321.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX SINGAPORE 069110

Ref: CS/EQI21002292/R1vf3q2

Date: 23/03/2021

Code: EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMM 9992E	<b>Veh. Inspected</b>	SMR 5408B
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DM21HO00225-JG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JOEL GOH	<b>Assign Date</b>	18/02/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	FERRARI CALIFORNIA T	<b>c.c</b>	3855
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	ZFF77XJC000206722	<b>Colour</b>	RED
<b>Odometer</b>	20080 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	245/35 ZR20	PIRELLI	6 mm
<b>L/H Front Tyre</b>	245/35 ZR20	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	245/35 ZR20	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	245/35 ZR20	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	07/02/2021	<b>Inspection Date</b>	18/02/2021
<b>Survey held at</b>	ITAL AUTO PL 30 LENG KEE RD SINGAPORE 159100		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 5408B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	AIR DUCT (SN)	CRACKED	1,914.82	1,914.82
1	COMPL.FRONT BUMPER (SN)	DEFORMED	17,654.35	17,654.35
1	BUMPER GRILLE (SN)	BENT	3,883.98	3,883.98
3	GRILLE FASTENER BRACKET @\$282.48 (SN)	BENT (2 PCS ONLY)	847.43	564.96
6	RIVET @\$3.89 (SN)	NECESSARY	23.34	23.34
4	RIVET @\$47.08 (SN)	NECESSARY	188.32	188.32
3	SCREW @\$18.84 (SN)	NECESSARY	56.53	56.52
2	PARKING SENSOR @\$517.21 (SN)	CRACKED (1 PC ONLY)	1,034.42	517.21
2	CENTRAL SENSOR BRACKET @\$189.72 (SN)	NECESSARY (1 PC ONLY)	379.44	189.72
1	CAVALLINO RAMPANTE BADGE (SN)	NECESSARY	132.15	132.15
1	FRONT ORNAMENT (SN)	NECESSARY	471.11	471.11
1	GASKET (SN)	NECESSARY	223.63	223.63
8	NUT @\$4.31 (SN)	NECESSARY	34.48	34.48
			26,844.00	25,854.59
<b><u>LABOUR</u></b>				
REMOVE AND REPLACE DAMAGED PARTS,FRONT BUMPER & ACCESSORIES,FRONT AIR INTAKE DUCTS,ETC.			15,360.00	13,440.00
SPRAY PAINTING FRONT BUMPER.			4,500.00	4,000.00
DIAGNOSTIC TESTS/TEST DRIVE,FRONT BUMPER PROTECTIVE FILM,NUMBER PLATE.			2,277.00	2,277.00
			22,137.00	19,717.00
<b>GRAND TOTAL</b>			<b>48,981.00</b>	<b>45,571.59</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>45,571.59</b>

Report Ref No. CS/EQI21002292/R1vf3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 09/02/2021 16:30 (SGT)  
Date of Accident ..... 07/02/2021 16:00 (SGT)  
Exact Location of Accident ..... 22 Dempsey Rd, Singapore 249679  
Additional Location Information ..... Dempsey Road  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMR5408B

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... BENEDICT PENG CHAN WEARN  
NRIC No ..... SXXXX147H  
Email Address ..... BCWPENG@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-91261586  
Alternative Phone No ..... +65-91261586

### VEHICLE PARTICULARS

Manufacturer ..... Ferrari  
Model ..... California  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car

### INSURANCE COMPANY

Name of Insurance Company ..... Etiqa  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... M0016335  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... HWEE PEIK HUM ANGELA  
NRIC No ..... SXXXX329B  
Date Of Birth ..... 02/06/1977  
Occupation ..... Indoor

Date Of Driving Pass .....	02/01/1998
Driving experience .....	23 YEARS AND 1 MONTH
Gender .....	Female
Mobile Number .....	(Phone) +65-96821630
Alt. Phone Number .....	-
Email Address .....	BCWPENG@GMAIL.COM
Address .....	26E PIERCE ROAD
Address complement .....	-
Postcode .....	248543
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Spouse
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Head to Rear
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other material or property damaged? .....	No
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-


#### CIRCUMSTANCES OF ACCIDENT

Please refer to statement attached. REPORT DELAYED AS COUNTERPARTY HAD INITIALLY REQUESTED FOR A PRIVATE SETTLEMENT.

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No
Was there any audio recorded? .....	No

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving towards the carpark and was waiting for the car in front to move forward while suddenly car B reversed to give way to another car turning out of the carpark. Car B hit into my front of the car as a result of this.

Owner of Car B - Wilson Ng Ah Yong

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/TIN No.:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SMR 5408B

## INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 5408B

RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

