

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21002295/UTD3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001571167
Claimant		
Vehicle No : SLU73L	Insured Vehicle No :	XE485Z
Date of Loss: 04/02/2021	Nature of Claim:	TP
		Claim No: 253417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU73L		
Make & Model:	AUDI A5, 2.0 L TFSI QUATTRO (A)	Engine No:	CDN212660
Reg. Date:	23/08/2011 (Man. Year: 2011)	Chassis No:	WAUZZZ8T7BA094727
Colour:	Black	Odometer:	95403 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35R19	Rear Tyre Size:	255/35R19
Front Left Side:	Summerstar 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Summerstar 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,859.19	2,515.07	6,344.12	71.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	750.00	1,190.00	61.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,799.19	3,265.07	7,534.12	69.77
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	10,799.19	2,600.00	8,199.19	75.92

INSPECTION

Date of Assignment:	18/02/2021	
Date Inspected:	18/02/2021	Inspected At:
		Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Mar 2021)	
Parts:	N/A	AUDI A5 2.0 L TFSI QUATTRO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU73L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Warped/Torn	2,215.25 FL	*1,652.00 FL
2	1		*FRONT BUMPER BRACKET-RH	Not Necessary	125.50 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER-RH	Not Necessary	65.00 FL	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
5	1		*FRONT FENDER-RH	Dented	1,085.00 FL	*921.32 FL
6	1		*FRONT FENDER INNER SHIELD-RH	Torn	246.55 FL	*166.20 FL
7	15		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	82.50 FL	*- FL
8	1		*FRONT HEADLAMP-RH	Not Necessary	3,863.75 FL	*- FL
9	1		*FRONT HEADLAMP BRACKET-RH	Not Necessary	105.00 FL	*- FL
10	1		*RIM	Not Necessary	1,200.00 FS	*- FS
11	1		*TYRE	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,643.55	2,794.52
- List Item Discount on L Items 10.00/10.00% (S\$)	784.36	279.45
Total Parts (S\$)	8,859.19	2,515.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKING FRONT ELECTRICAL WIRING	New	120.00	20.00
2	TO REMOVE,REFIX AND RESET BUMPER PDC	New	120.00	0.00
3	TO RESPRAY UNDERCOATING	New	100.00	30.00
4	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	800.00	400.00
5	PANEL BEATING,REMOVE AND REPLACING ABOVE PARTS	New	800.00	300.00
			Gross Labour Cost (\$\$)	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >