



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2105892

INV Date 20/08/2021

Reference CC4/LPC21002297/Ggs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 7573S
Insured Veh. SMQ 5625X
Claim No. 20/21/21/VP05/024250
Policy No. Z20VP05027873
Accident Date 17/02/2021
Inspection Date 18/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21002297/Ggs3q2 Date: 20/08/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMQ 5625X	Veh. Inspected	SHA 7573S	
Policy No.	Z20VP05027873	Coverage (\$)	0.00	
Claim No.	20/21/21/VP05/024250	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	18/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDKB3FU103091132	Colour	BLUE	
Odometer	92802 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2021	Inspection Date	18/02/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7573S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER BEAM	BENT	318.80	318.80
1	REAR BUMPER TOW COVER	CUT	82.30	82.30
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	TAILLAMP ASSY RH UPPER	CRACKED	557.90	557.90
1	TAILLAMP ASSY RH LOWER	CUT	548.40	548.40
1	BOOTLID COVER	BENT	1,126.60	1,126.60
1	BOOTLID EMBLEM -PRIUS	NECESSARY	60.80	60.80
1	BOOTLID EMBLEM -HYBIRD	NECESSARY	52.40	52.40
1	BOOTLID EMBLEM -STAR	NECESSARY	52.90	52.90
1	BOOTLID UPPER -GLASS (ADDITIONAL)	NECESSARY	1,778.30	1,778.30
1	BOOTLID LOWER -GLASS (ADDITIONAL)	NECESSARY	1,569.70	1,569.70
1	ANTENNA ELECTRIC KEY (ADDITIONAL)	NOT WORKING	57.00	57.00
1	COVER -REAR FLOOR (ADDITIONAL)	CRACKED	220.50	220.50
1	BOOTLID PANEL SUB-OUTER (ADDITIONAL)	BUCKLED	889.70	889.70
	LESS 25% DISCOUNT		-2,087.13	-2,087.16
			6,261.37	6,261.34
	<u>SPECIAL NETT ITEMS</u>			
1	BOOTLID COMFORTDELGRO LOGO (SN)	NECESSARY	30.00	30.00
1	BOOTLID COMFORTDELGRO TEL.NO (SN)	NECESSARY	30.00	30.00
1	BOOTLID APPS LOGO (SN)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			285.70	150.00
	<u>LABOUR</u>			
	RENEW REAR WINDSCREEN GLASS . (ADDITIONAL)		120.00	120.00
	PANEL BEATING.		900.00	700.00
	SPRAYPAINT.		700.00	500.00
	CHECK WIRING .		50.00	30.00

Report Ref No. CC4/LPC21002297/Ggs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE/REFIL REVERSE SENSOR .		80.00	40.00
	REMOVE/REFIT FRT SUSPENSION DAMAGED PARTS.	NOT NECESSARY	150.00	-
	REMOVE/REFILL AIRCON PARTS AND GAS.	NOT NECESSARY	120.00	-
			2,170.00	1,390.00
GRAND TOTAL			8,717.07	7,801.34
RECOMMENDED COST OF REPAIRS				7,801.34

Report Ref No. CC4/LPC21002297/Ggs3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7573S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7573S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7573S

RE-INSPECTION

