

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002302/R1TF3E2

Date: 24/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070161337
Claimant Vehicle No : SLG4052U Insured Vehicle No : SJZ7683C
Date of Loss: 10/02/2021 Nature of Claim: TP Claim No: 9685395735SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG4052U**
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGGU221313
Reg. Date: 29/09/2016 (Man. Year: 2016) Chassis No: KMHD841CMHU254937
Colour: Blue Odometer: 58969 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/02/2021
Date Inspected: 22/02/2021 Inspected At: Champion Auto Air-conditioner Co (HQ)
1007 BUKIT MERAH LANE 3, #01-01
Singapore 159721
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*REAR BUMPER	Cracked	0.00 F	*- F
3	1		*REAR BUMPER LOWER GARNISH	Cut	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*BOOTLID	Bent	0.00 F	*- F
8	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >