

# T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TTH AUTO

BLOCK 516 JELEPANG ROAD

#09-257 SINGAPORE 670516

Attention : Motor Claim Department

Not Authorised  
1/12/21  
Purong After Pain  
5 days

Estimate : ES003419

Date : 11/02/2021

Vehicle Num. : GBB7087U

Make/Model : NISSAN URVAN

Chassis/Eng# :

Accident Date : 11/02/2021

Claim No. :

Reference :

Policy No. : D20MCV0006901

| S/N                      | Quantity  | Particular                             | Unit Price | Amount S\$ |
|--------------------------|-----------|----------------------------------------|------------|------------|
| NETT ITEMS :             |           |                                        |            |            |
| 1.                       | 1         | FRONT SIDE PANEL LH                    |            | 525.50     |
| 2.                       | 1         | FRONT HEAD LAMP L/H                    |            | 458.70     |
| 3.                       | 1         | FRONT BUMPER                           |            | 541.00     |
| 4.                       | 1         | FRONT BUMPER SIDE RETAINER LH          |            | 116.10     |
| 5.                       | 1         | FRONT BUMPER SIDE SPORT LAMP COVER L/H |            | 130.10     |
| 6.                       | 1         | FRONT GRILLE                           |            | 475.70     |
| 7.                       | 1         | FRONT LOWER ARM LH                     |            | 220.50     |
| 8.                       | 1         | FRONT WHEEL BEARING HUB ASSY LH        |            | 596.10     |
| 9.                       | 1         | FRONT STEERING RACK END PINION ASSY    |            | 1,950.20   |
| 10.                      | 2         | FRONT STABILIZER BAR LINK LH/RH        |            | 103.00     |
| 11.                      | 2         | AUTO GEAR BOX OIL PIPE RUBBER HOSE     | 51.50      | 352.00     |
| 12.                      | 1         | AUTO GEAR BOX OIL PIPE                 | 176.00     | 131.60     |
| 13.                      | 1         | FRONT TYRE LH                          |            | 220.00     |
| 14.                      | 1         | STEP GARNISH LH                        |            | 416.30     |
| 15.                      | 4         | STEP GARNISH CLIPS                     | 5.50       | 22.00      |
| 16.                      | 8         | FRONT BUMPER CLIPS                     | 5.80       | 46.40      |
| Nett Total S\$ :         |           |                                        |            | 6,305.20   |
| SPECIAL NETT ITEMS :     |           |                                        |            |            |
| 1.                       | 1         | FRONT BUMPER SIDE SPORT LAMP L/H       |            | 323.70     |
| 2.                       | 2 (LH/RH) | FRONT ENGINE MOUNTING                  | 100.70     | 201.40     |
| 3.                       | 1 (L/H)   | FRONT GEAR BOX MOUNTING                |            | 191.10     |
| 4.                       | 2 (LH/RH) | FRONT SHOCK ABSORBER                   | 131.20     | 262.40     |
| 5.                       | 1         | FRONT KNUCKLE ARM LH                   |            | 351.50     |
| 6.                       | 1         | FRONT LOWER ARM BALL JOINT LH          |            | 91.70      |
| 7.                       | 1         | AUTO GEAR BOX OIL COOLER               |            | 597.40     |
| 8.                       | 1         | FRONT TYRE RIM LH                      |            | 237.90     |
| Special Nett Total S\$ : |           |                                        |            | 2,257.10   |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CONTINUE / ...

# T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

TTH AUTO

BLOCK 516 JELEPANG ROAD

#09-257 SINGAPORE 670516

Attention : Motor Claim Department

Estimate : ES003419

Date : 11/02/2021

Vehicle Num. : GBB7087U

Make/Model : NISSAN URVAN

Chassis/Eng# :

Accident Date : 11/02/2021

Claim No. :

Reference :

Policy No. : D20MCV0006901

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

LABOUR :

1. TOWING

60.00 50

2. CHECK & REPAIR WIRING

80.00 20

3. SPRAY ANTI-RUST COATING

150.00 x

4. REMOVE & REPLACE THE NEW FRONT L/H UNDERCARRIAGE PARTS

550.00 7

5. CHECK & REPLACE THE NEW TRANSMISSION COOLER & TOP TRANSMISSION OIL

280.00 1800

6. COMPUTER WHEEL ALIGNMENT

120.00 60

7. SPRAY PAINT ON AFFECTED PORTIONS

750.00 500

8. LABOUR CHARGE FOR REPAIRING, ADJUSTING, KNOCKING, WELDING THE DAMAGED PARTS, STRAIGHTEN THE ABOVE

950.00 400

Labour Total S\$ :

2,940.00

ingDollars : Eleven Thousand Five Hundred Two & Cents Thirty Only

E. & O.E.

Total S\$ : 11,502.30

T & B MOTOR REPAIRS SERVICES PTE LTD