



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002304/Uvf3q2	
			Date: 02/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMM 7618A	Veh. Inspected	SLR 8798S
	Policy No.	D20MTOV01009435	Coverage (\$)	0.00
	Claim No.	CMTD2100506/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	18/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS HYBRID (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZVW518036218	Colour	WHITE
	Odometer	75779 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	NEUTON	6 mm
	L/H Front Tyre	195/65 R15	NEUTON	6 mm
	R/H Rear Tyre	195/65 R15	NEUTON	6 mm
	L/H Rear Tyre	195/65 R15	NEUTON	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/02/2021	Inspection Date	18/02/2021
	Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	