# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Cecilia Low Date: 23 Mar 2021

# **Preliminary Advice**

Insured Vehicle No : GBE2284J

 TP Vehicle No
 : GK9787M
 Accident Date
 : 07/02/2021

 Make
 : NISSAN NV350
 Assignment Date
 : 18/02/2021

Date of Inspection : 26/02/2021 Est. Duration of Repair : 4

Inspection At : RIVERVIEW AUTO SERVICES PTE LTD (HQ)

10, ANG MO KIO INDUSTRIAL PARK 2A, #04-07 AMK AUTOPOINT

SINGAPORE 568047

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,695.33
Revised Amount	:S\$	1,580.82
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,580.82
Lump Sum Repair	:S\$	1,250.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir let us have your authorisation.	าdly
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.	
)	Other comments:	