



30	1	RR BUMPER REVERSE SENSOR WIRE HARNESS <i>New</i>	\$ 388.00	+
31	1	RR TAILLAMP RH <i>3M</i>	\$ 561.00	+
32	1	RR TAILLAMP LH <i>3M</i>	\$ 561.00	+
33	1	RR END PANEL <i>Repair</i>	\$ 409.00	+
34	1	RR END PANEL AIR DUCT - VENT <i>New</i>	\$ 126.00	+
35	1	RR END PANEL TOP GARNISH <i>could</i>	\$ 251.00	-
36	1	RR SPARE TYRE PANEL <i>New</i>	\$ 1,411.00	+
37	1	RR FENDER PROTECTOR RH	\$ 132.00	+
38	1	RR FENDER PROTECTOR LH	\$ 132.00	+
39	1	RR FENDER INNERSHIELD LH	\$ 201.00	+
40	1	RR FENDER INNERSHIELD RH	\$ 201.00	+
41	1	RR EXHAUST SILENCER BOX	\$ 1,653.00	+
42	1	RR EXHAUST SILENCER BOX MOUNTING <i>New</i>	\$ 155.00	+

6507  
5856.30

Parts Total: \$ 17,393.00  
Less 10%: \$ 1,739.30  
Total: \$ 15,653.70

**Labour**

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00 <i>600</i>
2	Carry out spray painting on accident affected area RR BUMPER, RR TAILGATE, RR END PANEL, RR FENDER RH, RR FENDER LH	\$ 1,000.00 <i>600</i>
3	To conduct anti rust of under carriage tuff coat	\$ 80.00 <i>60</i>
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 100.00 <i>30</i>
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 200.00 <i>60</i>
6	To remove and refix reverse sensor and conduct test	\$ 80.00 <i>50</i>
7	To remove and refix reverse camera	\$ 80.00 <i>50</i>
8	To conduct transfer of parts from old tailgate to new tailgate	\$ 200.00 <i>80</i>
9	To remove and refix rear tail gate windscreen	\$ 180.00 <i>120</i>
10	To conduct water leakage test after repairs of vehicle	\$ 60.00 <i>+</i>

1650

Labour Total: \$ 2,980.00

**Others**

No.	Other Description	Price (SGD)
1	RR BUMPER CLIP <i>New</i>	\$ 40.00 ✓
2	RR END PANEL GARNISH CLIP <i>New</i>	\$ 40.00 <i>20</i>
3	RR TAILGATE INNER TRIM CLIP <i>New</i>	\$ 40.00 +
4	RR NUMBER PLATE <i>New</i>	\$ 60.00 +
5	RR BODYSEAL <i>New</i>	\$ 60.00 +
6	RR TURBO EMBLEM <i>3M</i>	\$ 100.00 -
7	RR GERMANY LOGO <i>3M</i>	\$ 100.00 -
8	RR WINDSCREEN SEALANT <i>3M</i>	\$ 65.00 -

<u>9</u>	1	RR WINDSCREEN INNER SEAL	<i>New</i>	\$	40.00
<u>10</u>	1	RR WINDSCREEN SOLAR FILM	<i>the m</i>	\$	200.00

*365*

Other Total: \$ 745.00

TOTAL: \$ 19,378.70  
 GST (7%): \$ 1,356.51

GRAND TOTAL : \$ 20,735.21

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor  
 KELVIN CHEW  
 HP: 8292 5595

*Adrian Wong*  
*18/02/21*

*05 Days ✓*

*Total: 7871.30*

*H/S : 6.2K ✓*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: