

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SGZ2402R

Model: Toyota Altis

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear L/H fender / CMY	\$ 900.00 /
1	Rear L/H smaller fender / CMY	\$ 400.00 250
1	Left taillamp / CMY	\$ 800.00 350
1	Rear bumper / CMY	\$ 800.00 612
1 / 2	Rear bumper retainer / BK	\$ 320.00 70
1	Rear end panel X R	\$ 2,000.00 X
1	Rear boot lock X Svc	\$ 550.00 X
1	Rear tailgate X R	\$ 1,100.00 X
1	Rear tailgate bracket X Svc	\$ 250.00 X
1	Rear bumper top step garnish X Svc	\$ 300.00 X
1	Rubber moulding X Svc	\$ 80.00 X

2,182
- 25%
1,636.50

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 7,500.00

c/f: \$ 7,500.00

Special Nett Items

AMT S\$

1	Rear bumper Panel clip <i>NEC</i>	\$ 150.00	<i>30</i>
		<u>\$ 150.00</u>	<i>30</i>

S/N. Labour Charges

1	Remove and refit Panels	\$ 600.00	
2	Apply tuff kote	\$ 300.00	<i>40</i>
3	Remove, refit and replaced damage and check up rear electrical wiring	\$ 150.00	<i>30</i>
4	Remove and refit inner garnishes trim to assist repair	\$ 200.00	<i>30</i>
5	To Panel Beating	\$ 600.00	<i>/</i>
6	To Respray Painting	\$ 900.00	<i>700</i>
		<u>\$ 2,750.00</u>	<i>1,400</i>

GRAND TOTAL

\$ 10,400.00

Repair dy 4dys

L/S

After paint photo

Sun Pin (LKL)

19/02/2021

TP without prejudice

Sunpin@lkkauto.com

1,636.50
30

1,400

3,066.5

- 2090

2,453.20

4/5

\$ 2,450

4days