



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21002316/Qtf3q2	
			Date: 23/03/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 5584Z	Veh. Inspected	SGZ 2402R
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VC05/024248	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	18/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	MR053ZEC107154199	Colour	SILVER
	Odometer	203630 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/70 R14	YOKOHAMA	6 mm
	L/H Front Tyre	185/70 R14	YOKOHAMA	6 mm
	R/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm
	L/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/02/2021	Inspection Date	19/02/2021
	Survey held at	AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	