



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2101892

INV Date 23/03/2021

Reference CS/EQI21002325/Avf3q2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. WPX 2000

Insured Veh. SGV 3887P

Claim No. DM21HO00229-JG

Policy No.

Accident Date 09/02/2021

Inspection Date 22/02/2021

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Ref: CS/EQI21002325/Avf3q2 Date: 23/03/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGV 3887P	Veh. Inspected	WPX 2000
Policy No.		Coverage (\$)	0.00
Claim No.	DM21HO00229-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	18/02/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA ACCORD	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	PMHCP26408D603416	Colour	BLACK
Odometer	177639 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	NEXEN	6 mm
L/H Front Tyre	245/40 R18	NEXEN	6 mm
R/H Rear Tyre	245/40 R18	NEXEN	6 mm
L/H Rear Tyre	245/40 R18	NEXEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/02/2021	Inspection Date	22/02/2021
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WPX 2000

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	685.40	685.40
2	REAR BUMPER SIDE HOLDER @\$35.00	N/S NECESSARY	70.00	35.00
2	REAR BUMPER EXHAUST CHROME @\$125.00	NOT NECESSARY	250.00	-
1	REAR BUMPER REINFORCEMENT	BENT	294.20	294.20
2	REVERSE SENSOR @\$195.00	DAMAGED (1 PC ONLY)	390.00	195.00
2	TAILLAMP @\$286.50	N/S CRACKED	573.00	286.50
2	TAILLAMP LOWER BRACKET @\$35.00	NOT NECESSARY	70.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	598.40	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	241.40	-
	LESS 20% DISCOUNT		-634.48	-299.22
			2,537.92	1,196.88
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER LOWER SPOILER (SN)	DAMAGED	1,200.00	600.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			1,310.00	630.00
	<u>LABOUR</u>			
	PANEL BEATING.REMOVE AND REFIT PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		600.00	600.00
	WIRING CHECK.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO SPRAY TUFF COAT.		150.00	40.00
	TO REMOVE UPHOLSTERY.		150.00	30.00
			1,650.00	1,150.00
	GRAND TOTAL		5,497.92	2,976.88

Report Ref No. CS/EQI21002325/Avf3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00
---	--	--	-----------------

Report Ref No. CS/EQI21002325/Avf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



**SINGAPORE
POLICE FORCE**



T/20210210/2082

1 of 4

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20210210/2082

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/02/2021 15:15		Vide Report No.:		Station Diary No.: 12	
Informant's Particulars					
Name of Informant: TAN WEE KEONG			Address: APT BLK 461 #10-1168 Ang Mo Kio Avenue 10 SINGAPORE		
ID Type / ID No.: FIN NO / F8034179L			Contact No.: Home/Office: Mobile: 92387953		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 40	Date of Birth: 28/03/1980	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: SUPERVISOR			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/02/2021 15:00	Type of Location: X-Junction
Location: SERANGOON NORTH AVENUE 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGV3887P	Car				Seriously Damaged	2
SKM143Y	Car				Slightly Damaged	0
WPX2000	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Driver			
Name	NG SEE BAH	ID No.	S0221241B
Related Vehicle	SGV3887P (Car)	Contact No.	97477398
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN SWEE KOK	ID No.	S8006554Z
Related Vehicle	SKM143Y (Car)	Contact No.	0
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN WEE KEONG	ID No.	F8034179L
Related Vehicle	WPX2000 (Car)	Contact No.	92387953
Hospital/Clinic	TECK GHEE CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	10/02/2021	Date Discharge	10/02/2021
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

On 09/02/2021 at about 1500hrs, my black Honda Accord, WPX2000 was stationary before the traffic light junction at the 2nd of 3 lane road along Ang Mo Kio Avenue 3 towards Serangoon North Avenue 3. Subsequently, I felt an impact from behind and my vehicle was moved forward. My body then swing forward and I waited for about 1 minute before alighting from my vehicle. Thereafter, I realized that it was a chain collision involving 3 vehicles and the second vehicle, black Toyota Vios, SGV3887P had collided onto my rear portion. Upon checking with all the drivers, the third driver of white BMW SKM143Y, informed that his brake was faulty as such, he is unable to stop in time. Due to the impact, my vehicle rear bumper was cracked and dented in. My vehicle is not installed with any in-car camera and so far, I do not have any witnesses. After the accident, I felt unwell and decided to seek medical treatment at Teck Ghee Clinic and was issued with 3 days MC from 10/02/2021 to 12/02/2021. Traffic light was red and in my favour.



**SINGAPORE
POLICE FORCE**



T/20210210/2082

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 4

Report No. T/20210210/2082

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20210210/2082

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

4 of 4

Report No. T/20210210/2082

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Staff Sgt HEAP ZHI YONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

10/02/2021 15:15

Classification Of Case:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WPX 2000

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WPX 2000

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

