

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No.: 53231488C

Adrian
LKC
ALG

08/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPALG.
Cecilia.

Accident date:

Estimated repair cost for vehicle no: SKW7194B HONDA SHUTTLE 1.5G CVT 15'

CHASSIS: GK81000669

S/n	Qty	Items	U/price	Amount
16	1	Rear Boot Lid <i>Distorted</i>		\$1,193.40
17	2	Rear Boot Lid Hinge <i>2 pieces</i>	\$55.10	\$110.20
18	2	Rear Boot Lid Shock Absorber	\$165.90	\$331.80
19	1	Rear Boot Lid Emblem Logo <i>New</i>		\$37.40
20	1	Rear Boot Lid Shuttle Logo <i>New</i>		\$55.00
21	1	Rear Boot Lid Number Plate <i>New</i>		\$50.00
22	2	Rear Boot Lid Number Plate Lamp <i>New</i>	\$48.60	\$97.20
23	1	Rear Boot Lid Camera (Special Nett) <i>Damaged</i>		\$680.00 380(SN)
24	1	Rear Boot Lid Center Chrome Moulding <i>Cracked</i>		\$383.10
25	2	Rear Boot Lid Side Reflector <i>Cracked</i>	\$340.80	\$681.60
26	1	Rear Boot Lid Windscreen Seal <i>New</i>		\$76.70
27	2	Rear Boot Lid Windscreen Side Moulding <i>New</i>	\$151.80	\$303.60
28	1	Rear Boot Lid Inner Lock <i>Jammed</i>		\$158.90
29	1	Rear Boot Lid Inner Rubber <i>lit</i>		\$108.60
30	1	Rear Boot Lid Inner Trim Board <i>Cracked</i>		\$320.20
31	2	Rear Tail Lamp <i>Cracked</i>	\$570.50	\$1,141.00
32	4	Rear Tail Lamp Clip <i>New</i>	\$8.00	\$32.00
33	2	Rear Tail Lamp Lower Bracket <i>New</i>	\$210.80	\$421.60
34	1	Rear Bumper <i>Distorted</i>		\$1,209.60
35	2	Rear Bumper Side Retainer <i>New</i>	\$26.50	\$53.00
36	10	Rear Bumper Clip <i>New</i>	\$3.90	\$39.00
37	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00 200(SN)
38	1	Rear Bumper Towing Cover <i>Distorted</i>		\$25.00
39	2	Rear Bumper Side Reflector <i>Cracked</i>	\$45.00	\$90.00
40	2	Rear Bumper Side Reflector Cover <i>Cracked</i>	\$45.30	\$90.60
41	1	Rear End Panel <i>Distorted</i>		\$631.50
42	1	Rear End Panel Top Garnish <i>Del</i>		\$155.50
43	1	Rear End Panel Lock Switch <i>New</i>		\$159.20

44	2	Rear Fender <i>Regrs</i>	\$1,210.90	\$2,421.80	+
45	2	Rear Fender Inner Trim Board <i>cracked</i>	\$455.60	\$911.20	✓
46	16	Rear Fender Inner Trim Board Clip <i>ne</i>	\$6.50	\$104.00	60
47	1	Rear Spare Tyre Panel <i>Buckled</i>		\$1,056.20	✓
48	1	Rear Spare Tyre Panel Top Cover <i>Delid</i>		\$655.00	585.
49	1	Rear Spare Tyre Panel Inner Top Cover <i>Not a</i>		\$608.00	+
50	1	Rear Spare Tyre Panel Rubber Cover <i>Ne n</i>		\$286.00	+
51	1	Rear Spare Tyre Panel Storage Box <i>Delid</i>		\$322.00	✓
52	1	Rear Spare Tyre Panel Foam Storage Box <i>cracked</i>		\$265.00	✓
53	1	Rear Spare Tyre Panel Spanner Box <i>Ne n</i>		\$295.40	+
54	1	Rear Spare Tyre Panel & End Panel Sealant <i>Ne n</i>		\$450.00	+
56	1	Rear Exhaust <i>Bent</i>		\$788.60	✓
57	1	Rear Center Exhaust <i>Not Bent</i>		\$988.00	✓
58	2	Rear Exhaust Mounting <i>Ne n</i>	\$28.00	\$56.00	+
59	1	Rear Exhaust Aluminium Cover <i>Not a</i>		\$107.60	+

11,895.50

9516.40

~~11,700.50~~ Subtotal :- \$18,330.50

~~9,120.40~~ S.N: 580

Labour charges

To remove & refit cushion	\$280.00	180
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear & center exhaust	\$380.00	160
To remove & refit rear camera	\$180.00	50
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To check wiring	\$100.00	30
Towing fee	\$150.00	x
Tuff kote	\$150.00	120
Panel beating	\$2,400.00	1400
Spray painting	\$2,000.00	1250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary 397.60
Total: 13,506.40
M/S: 10.8K
10 Days
Subtotal :- \$5,910.00

10.8K

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

16/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 07/02/2021

Estimated repair cost for vehicle no: SKW7194B HONDA SHUTTLE 1.5G CVT 15'

CHASSIS: GK81000669

S/n	Qty	Items	U/price	Amount
1	2	Rear Bumper Foam <i>crushed</i>	\$65.00	\$130.00 ✓
2	1	Rear Tail Lamp Panel <i>dented</i>		\$315.00 ✓
3	1	Rear Spare Tyre Panel Storage Box Cover <i>crushed</i>		\$52.00 ✓

Subtotal :- \$497.00

497
Supplementary: 397.60