



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SMT8152H

Model : BMW

Damaged Area: (Front Right Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Not Authorized
dlaer
18/1/21
1/5 \$ 4000 /
3 days

Parts / Material :

1	Front Bumper	DD/2e 1357.90	\$ 2,680.15	✓
2	Front Bumper Centre Lower Garnish	11	\$ 268.92	X
3	Front Bumper Lower Side Grille RH	11	\$ 286.11	X
4	Front Bumper Fog Lamp RH	scr	\$ 275.10	✓
5	Front Bumper Centre Mount	11	\$ 286.32	X
6	Front Bumper RH Top Mount	11	\$ 254.65	X
7	Front Bumper RH Lower Mount	11	\$ 241.55	X
8	Front Bumper Sensor Ring Set	11	\$ 45.72	X
9	Front Bumper Angle Sensor @ 286.00	shotel 215	\$ 1,144.00	1pc
10	Front Bumper Rivet	11	\$ 21.00	✓
11	Front Bumper Body Nut	11	\$ 9.00	X
12	Front Bumper Repair Kit	11	\$ 112.20	X
13	Front Bumper Logo	11	\$ 145.82	✓
14	Front Bumper Centre Grille Garnish @ 357.32	11	\$ 714.64	X
15	Front Fender RH	2	\$ 1,568.32	X
16	Front Fender Inner Shield RH	11	\$ 213.30	X
17	Front Fender Inner Shield Expanding Rivets	11	\$ 19.80	X
18	Front Headlamp Nozzle Garnish RH	11	\$ 198.41	X
19	Front Headlamp Nozzle RH	11	\$ 296.42	X
20	Front Headlamp RH	scr	\$ 2,682.45	✓
21	Front Door RH	11	Repair	X
22	Front Rim RH	11	\$ 1,832.65	X

Parts : \$ 13,296.53

Less Parts 5% : \$ 664.82

Total Parts : \$ 12,631.70

Special Net Items :

Front Number Plate W/Garnish	11	\$ 80.00	X
Front Tyre RH	11	\$ 620.00	X

Total S/N Parts : \$ 700.00

Labour :

To Remove, Repair & Renew Affected Accident Areas	\$ 1,200.00	200
To Putty, Spray Paint on Front Affected Accident Areas	\$ 1,200.00	400
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Front Door Components	11 \$ 150.00	X
To Conduct All Wheel Alignment	11 \$ 150.00	X
To Diagnostic & Reset to Specification	11 \$ 450.00	X
To Rust Proof Affected Areas	11 \$ 100.00	X

Total Labour : \$ 3,300.00

TOTAL PARTS : \$ 12,631.70

2. 4619.45
5-2
4288.47
5058.47

TOTAL SPECIAL NET ITEM : \$ 700.00
TOTAL LABOUR : \$ 3,300.00
TOTAL REPAIR COST : \$ 16,631.70

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The information contained herein is correct as at 18 Feb 2021

OK