



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM21002334/Ubs3q2 Date: 07/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 3693S	Veh. Inspected	GX 6100X	
Policy No.	VPA/P1398851	Coverage (\$)	0.00	
Claim No.	S1M031SI	Excess (\$)	0.00	
Assign From		Assign Date	18/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LITEACE (M)	c.c	2184	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	CR425009473	Colour	SILVER	
Odometer	208224 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165 R13	FALKEN	5 mm	
L/H Front Tyre	165 R13	FALKEN	5 mm	
R/H Rear Tyre	165 R13	FALKEN	5 mm	
L/H Rear Tyre	165 R13	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2021	Inspection Date	18/02/2021	
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	