



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21002336/Qqd3n2	Date: 26/04/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 169M	Veh. Inspected	SKG 2525Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009118/ST	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	18/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	BMW 218I	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA2A32080VZ53284	Colour	BLUE	
Odometer	70727 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/02/2021	Inspection Date	19/02/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	