

Section A - Accident Details

Registration Number	SHC4576T
Case Reference Number	TAX/02/21/2038
Registration Date	10/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM BEE SENG
Type of Accident	Side Swipe
Accident Date and Time	14/2/2021 12:45 PM
Accident Reported Date and Time	15/2/2021 4:12 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109754
Special Instruction to ARC, if any	TP /TOWED \$60
Prepared Date and Time	16/2/2021 9:20 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,476.00	\$400.00
Total Spare Part Cost	\$6,339.15	\$1,080.18
Total Other Cost	\$684.00	\$80.00
TOTAL COST	\$9,175.15	\$1,760.18
Lump Sum Total	\$9,200.00	\$1,750.00 (L/S)
Number of Repair Days	6.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	16/02/2021 4:14 PM	16/02/2021 3:40 PM
Signature		
Remarks		L/S, After paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2102-0390	Invoice Number	
Quotation Date	26.02.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION RH	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$84.00	\$60.00
Total Other Costs	\$684.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	R
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given	SVC
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	SVC
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	SVC
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check	SVC
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given	SVC
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	SVC
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	SVC
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given	SVC
		82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	SVC
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	CRA

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/02/2021

User ID : PohSuan

53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	X	SVC
53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given	X	SVC
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X	SVC
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X	SVC
51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given	X	SVC
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X	SCR
53801-47050	FENDER FRT/RH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	X	R
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	X	Nec
53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X	SVC
53851-47040	FENDER LINER PAD, FR WHEEL. RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X	SVC
42611-47140	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X	SVC
43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X	SVC
87910-47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given	X	SVC
81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X	SVC
879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	100.00	\$0.00	Replace	Old Damage	X	SVC
Total			\$10,155.65		\$1,350.23				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1350.23 /

- 20%

1080.18 /

+ 200.00 /

+ 480.00 /

1760.18 /

45 \$1750/-

2 days