

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
 TEL: 64193000 FAX: 68357416
 ATTN: Motor Claim Department

Estimate No: EST2100059
Date: 23 Feb 2021
Veh Reg No: SKB566T
Make/Model: VOLKSWAGEN NEW BEETLE 1.6 A 6SPD
Chasis No: WVWZZZ9CZ9M558290
Reg. Date: 04/06/2009
Your Ref No: SML6243J

Claim Type: Third Party
Accident Date: 12/02/2021
TP Veh Reg No: SML6243J

Xiao Tony.

Estimate Repair Cost to Vehicle No :SKB566T

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC FRT DOOR RH <i>Dented</i>	1,999.30	1,695.00
2	1 PC FRT DOOR OUTER MOULDING RH <i>3 ne</i>	167.70	✓
3	1 PC FRT DOOR GLASS CHANNEL RH <i>3 ne</i>	188.90	✓
4	1 PC FRT DOOR GLASS REGULATOR ASSY RH <i>Damaged</i>	510.70	✓
5	1 PC FRT DOOR FRAME BLACK GARNISH RH <i>Neu</i>	99.70	✓
6	1 PC FRT DOOR TRIM RH <i>Could</i>	900.70	825
7	1 PC RH SIDE ROKER PANEL <i>Dented</i>	1,800.60	1,380.00
8	1 PC FRT FENDER RH <i>Debond</i>	861.90	✓
		6,529.50	
	<i>5172.30</i> <i>4655.07</i>	652.95	Less 10% 5,876.55
Labour			
9	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	900.00
10	1 TO SPRAY PAINTING	1,000.00	750.00
11	1 TO SPRAY UNDERSEAL	80.00	✓
12	1 TO REMOVE AND REFIT CUSHION	80.00	x
13	1 TO REMOVE AND REPLACE RH DOOR TRIM	80.00	40
14	1 TO REMOVE AND REFIT RH DOOR GLASS	100.00	40
		2,340.00	2,340.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2100059
Date: 23 Feb 2021
Veh Reg No: SKB566T
Make/Model: VOLKSWAGEN NEW
BEETLE 1.6 A 6SPD
Chasis No: WVWZZZ9CZ9M558290
Reg. Date: 04/06/2009
Your Ref No: SML6243J

Claim Type: Third Party
Accident Date: 12/02/2021
TP Veh Reg No: SML6243J

Estimate Repair Cost to Vehicle No :SKB566T

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 8,216.55

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND TWO HUNDRED SIXTEEN AND CENTS FIFTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

Aliyap
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adwin Lj
15/02/21 4/5.

05 Days.

total: 6265.07

L/sum \$5,300.00