



Automobile Integrated Management Pte Ltd
Co. & G S T Reg no. 201605297G
Office: 61 Ubi Ave 2 #07-04 Automobile Megamart Singapore 408898
Workshop: 23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933
Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: AC2021014/TP/SFK9850A-11.02.2021

Vehicle number: SFK9850A

Vehicle Make & Model: AUDI A3

Items	Qty	List Items	Amount \$
1	1	Front Bonnet <i>Amc</i>	1,689.90
2	1	Front bonnet lock <i>X</i>	180.95
3	1	Front bonnet safety lock <i>X</i>	115.60
4	1	Front bonnet damper <i>X</i>	191.55
5	1	Front bonnet insulator <i>X</i>	241.45
6	10	Front bonnet insulator clips @ 5.50 <i>X</i>	55.00
7	1	Front bumper <i>Re</i>	1,558.50
8	2	Front bumper fog lamps - L/R @ 281.50 <i>X</i>	563.00
9	2	Front bumper fog lamp covers - L/R @ 110.20 <i>X</i>	220.00
10	1	Front bumper tow cover <i>mis</i>	28.85
11	1	Front bumper sponge <i>?</i>	142.65
12	1	Front bumper reinforcement <i>?</i>	715.00
13	2	Front bumper side grids - L/R @ 68.85 <i>?</i>	137.70
14	2	Front fenders - L/R @ 816.50 <i>X</i>	1,633.00
15	1	Front grille assy <i>CEA</i>	1,260.00
16	2	Front headlamps - L/R @ 2455 <i>LH? BR.</i>	4,910.00
17	1	Front support panel <i>BT</i>	895.00
18	1	Air cleaner intake duct <i>?</i>	196.55
19	1	Air intercooler <i>?</i>	899.60
20	1	Air con condenser <i>?</i>	965.00
21	1	Air con discharge pipe <i>?</i>	481.50
22	1	Air con suction pipe <i>?</i>	411.50
23	1	Radiator assy <i>?</i>	860.50
24	1	Radiator top hose <i>X</i>	110.65
25	1	Radiator bottom hose <i>X</i>	121.60
26	1	Radiator auxiliary fan assy <i>?</i>	1,150.00
27	2	Horns @ 89.95 <i>?</i>	179.90
Sub-total			19,914.95
Less 5%			995.75
Total List			18,919.20

Vehicle number: SFK9850A

Vehicle Made & Model: AUDI A3

<u>Special Nett Items</u>			
28	1 set	Front no. plate	60.00
29	1 bot	Air con oil	65.00
30	1 bot	Radiator coolant	65.00
			190.00

<u>Labour charges</u>			
31	To check front electrical wiring	50.00	30
32	Towing charges	100.00	?
33	To diagnos, erase fault memory after repair	350.00	X nn
34	To remove, refix A/C condenser & refill A/C gas	180.00	120
35	To respray painting and etc	1,080.00	400
36	Panel beating, cut, weld remove & replacing above parts	1,050.00	600.
		Total Labour	2,810.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

21,919.20

5 Days.
Lump sum repair
After repair photos.
Gms Q: any.
82880282
19/2/2021
Excess: TBA
Not Authorised.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: