

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883
TEL: 65096584

TO	: INDIA INSURANCE	DATE	: 19/2/2021
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJV7948K		Veron.
VEHICLE MODEL	: TOYOTA ALTIS		
CHASSIS NO	: MR053ZEE106163066		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	SIONG / 97864483	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Del</i>	1	\$ 495.00	\$ 495.00
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 36.00	\$ 72.00
3	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 72.50	\$ 145.00
4	REAR BUMPER SPONGE <i>cut d</i>	1	\$ 129.50	\$ 129.50
5	REAR BUMPER REINFORCEMENT ROD <i>not new</i>	1	\$ 117.50	\$ 117.50
6	REAR BUMPER REINFORCEMENT BRACKET <i>LH Dented</i>	2	\$ 98.10	\$ 196.20
7	REAR END PANEL <i>Dented</i>	1	\$ 581.40	\$ 581.40
8	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 192.50	\$ 192.50
9	BOOTLID <i>Buckled</i>	1	\$ 695.60	\$ 695.60
10	BOOTLID LOCK <i>new</i>	1	\$ 189.20	\$ 189.20
11	BOOTLID WEATHERSTRIPE <i>ut</i>	1	\$ 195.50	\$ 195.50
12	BOOTLID REFLECTOR <i>new</i>	2	\$ 260.20	\$ 520.40
13	TAILLAMP <i>LH cracked, RH ut</i>	2	\$ 325.00	\$ 650.00
14	SPARE TYRE PANEL TOP COVER <i>new</i>	1	\$ 289.30	\$ 289.30

Toyota Logo } 42 ✓
 1.6 Emblem } 45 ✓
 Corolla Emblem } new 46 ✓
 Altis Emblem } 48 ✓

TOTAL PRICE: \$ 4,469.10
 LESS 25% \$ 1,117.27
 SUB TOTAL PRICE: \$ 3,351.83

3290.60
 2467.95

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00
3	REAR END PANEL TOP GARNISH CLIPS } new	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT	1 SET	\$ 80.00	\$ 80.00

5	BOOTLID REFLECTOR SPONGE GASKET <i>new</i>	2	\$ 20.00	\$ 40.00
6	TAILLAMP SPONGE GASKET <i>new</i>	2	\$ 20.00	\$ 40.00
			TOTAL :	\$ 510.00

340

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	<i>80</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>80</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO REMOVE AND REFIT REVERSE SENSOR	\$ 100.00	<i>50</i>	
5	TO REMOVE AND REFIT UPHOLSTERY	\$ 150.00	<i>60</i>	
6	TUFF COAT	\$ 150.00	<i>60</i>	
7	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	<i>60</i>	

TOTAL: \$ 3,000.00

1860

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,861.83

TOTAL LABOUR COST: \$ 3,000.00

TOTAL REPAIR COST: \$ 6,861.83

6997.58

total: 4667.85

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

h/s: 3.7K.

06 Days.

PART BY PART / LUMP SUM:

NO. OF DAYS:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: