



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0134/2021/KS  
**DATE** : 15-Feb-21  
**WIP** : 15279

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/2/2021**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

**OWNER'S NAME** : LIU JUN  
**ADDRESS** : BLK 867 TAMPINES ST 83  
#10-247  
SINGAPORE 520867  
**TELEPHONE** : HP +65 96988666  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2100364322-06  
**VEHICLE NO** : **SKL 8550 H**  
**MODEL CODE** : AUDI Q5 2.0 TFSI QU  
**MODEL YEAR** : 30/12/2013  
**ENGINE NO** : CNC 027633  
**CHASSIS NO** : WAUZZZ8R6EA040814  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Feb-21  
**PLACE OF ACCIDENT** : BEDOK RESERVOIR, SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLLE. SKL 8550 H**

<b>S/N</b>	<b>NATURE OF JOBS</b>		<b>ESTIMATED CHARGES</b>	<b>SURVEYOR'S RECOMMENDATIONS</b>
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGES.	S/N \$	280.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	
3	TO RESPRAY REAR BUMPER AND REAR BUMPER LOWER SPOILER..	\$	2,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 3,672.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 8550 H**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,798.00	
2	REAR BUMPER FIXING PARTS	1	\$ 166.00	
3	REAR BUMPER SPOILER	1	\$ 866.00	
4	REAR BUMPER CARRIER	1	\$ 681.00	
5	REAR BUMPER BRACKET HOLDER LH / RH	2	\$ 428.00	
6	REAR PARKING AID SENSOR	1	TBC	
7	REAR PARKING AID SENSOR SEAL RING	4	\$ 6.00	
8	REAR BUMPER TAILLIGHT	1	\$ 299.00	
9	SUNDRIES		\$ 200.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 4,444.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 3,672.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 8,116.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT