

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21002369/AGS3Q2
Date: 30/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070165261
Claimant Vehicle No :	SKP7300Z	Insured Vehicle No :	SJT2300Y
Date of Loss:	15/02/2021	Nature of Claim:	TP
		Claim No:	1275308330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP7300Z		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZRB345713
Reg. Date:	03/10/2014 (Man. Year: 2014)	Chassis No:	ZGE206012002
Colour:	White	Odometer:	169382 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,640.50	1,224.00	5,416.50	81.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,630.00	1,130.00	40.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,400.50	2,854.00	6,546.50	69.64
Approved Total (Overridden) (S\$)		2,300.00		

Nett Amount (S\$)	9,400.50	2,300.00	7,100.50	75.53
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,147.45		

INSPECTION

Date of Assignment: 18/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 5.0 days

Inspected At: Zero Gravity (Kaki Bukit)
2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub
Singapore 417921

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR (L/H/R)	Repair	1,360.00 FL	*- FL
2	1		*DOOR (L/H/F)	Repair	1,480.00 FL	*- FL
3	1		*DOOR (R/H/F)	Dented	1,480.00 FL	*1,172.00 FL
4	1		*DORO PILLAR (R/H/F)	Repair	485.00 FL	*- FL
5	1		*SIDE MIRROR (R/H/F)	Not Necessary	874.00 FL	*- FL
6	1		*DOOR ANTI SPLASH PLASTIC SEAL	Not Necessary	96.00 FL	*- FL
7	1		*DOOR INNER TRIM BOARD	Not Necessary	1,075.00 FL	*- FL
8	9		*DOOR INNER TRIM BOARD CLIP	Not Necessary	54.00 FL	*- FL
9	1		*DOOR CHECKER	Not Necessary	147.00 FL	*- FL
10	1		*DOOR HINGE (R/H/F LOWER)	Not Necessary	77.00 FL	*- FL
11	1		*DOOR HINGE (R/H/F UPPER)	Not Necessary	77.00 FL	*- FL
12	1		*DOOR WEATHERSTRIP (R/H/F)	Not Necessary	203.00 FL	*- FL
13	1		*DOOR CHANNEL BRACKET	Not Necessary	86.00 FL	*- FL
14	1		*DOOR INNER LOCK (R/H/F)	Not Necessary	635.00 FL	*- FL
15	1		*WINDOW REGULATOR (R/H/F)	Not Necessary	265.00 FL	*- FL
16	1		*FENDER (R/H/F)	Dented	460.00 FL	*460.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,854.00	1,632.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,213.50	408.00
Total Parts (\$\$)	6,640.50	1,224.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & REPLACING OF THE ABOVE	New	1,000.00	700.00
2	TO PUTTY AND RESPRAY AFFECTED PORTION	New	1,250.00	800.00
3	TO REMOVE ,TRANSFER & INSTALL RELATED COMPONENT	New	250.00	0.00
4	TO REMOVE AND REFIT COMPONENTS/ FACILITATE THE REPAIR	New	180.00	100.00
5	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	New	80.00	30.00
Gross Labour Cost (S\$)			2,760.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >