

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB8054 L

1 pc	Bootlid emblem	\$	27.00	} n
1 pc	Bootlid CRDi	\$	29.00	
1 pc	Boot lid lower garnish	\$	290.00	
1 pc	Rear bumper	\$	696.00	} n
1 pc	Rear bumper lower cover	\$	206.00	
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	
1 pc	Rear bumper inner sponge	\$	114.00	} n
1 pc	Rear bumper reinforcement	\$	607.00	
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	106.00	
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	} n
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	
		\$	2,297.00	
		Less 10%	\$	229.70
			\$	2,067.30

Taufhin 92495749
up 24/2/2020 1420
2 days 4/5 Resurvey after repair
taufhin@khen.com

S/NETT

1 set	Rear bumper clips	\$	48.00	30 net
1 set	Bootlid lower garnish clips	\$	60.00	x n
1 set	Bootlid stickers	\$	100.00	x n
1 set	Reverse sensor	\$	280.00	200?
1 pc	Rear bumper protector	\$	80.00	x n
	Sundry	\$	50.00	x n
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	x n
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	800.00	200
To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid		\$	800.00	200
To apply rustproofing on the repaired and replaced panels.		\$	120.00	x n
		\$	4,705.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: